

ASS. REC. BY:

REF:

AGZ 24090488/Kap3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

277K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PMV1007E

Yr Regn:

09, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1318

Colour

N. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

27669

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHM GK 38502S 218212

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175/65R15

R:

BS/DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

28/9/24

D.O.I.

22/9/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/9/11 Lm 83550d Car used to 8517.80, 71%

Date/Time, File Pass to?



: Prel. Report

1) 02/10/2024



: Final Report

Date/Time, File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) TP

3550

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)

EMI Solution Pte Ltd

160 Sin Ming Drive, (Sin Ming Autocity), #03-18/19, Singapore 575722

H/P: 9004 2254 (Derek Keh) Tel: 6456 0226 Fax: 6458 4500

Email: emaautosolution@singnet.com.sg

Not wither
L1 Rep @ 3550h
Recovery After Pains
5 days

Vehicle number: SMV1007E

Vehicle Made & Model: HONDA JAZZ

Qty List Items

1	Tailgate	845.20
1 set	Tailgate glass moulding	60.80
1	Tailgate outer garnish	
1	Tailgate emblem "JAZZ"	
2	Tailgate lamps - L/R @ 281.60	
1	Tailgate inner lock	108.20
1	Tailgate inner trim board	
1	Tailgate w/strip	105.40
2	Tailgate dampers @ 141.20	
2	Tailgate hinges @ 61.50	
2	Tailgate stoppers @ 12.20	
2	Taillamps - L/R @ 411.50	@ 350
1	Taillamp panel - LH	
1	Rear bumper	568
1	Rear bumper moulding - CTR	
2	Rear bumper side mouldings - L/R @ 86.60	
2	Rear bumper PDC sensors @ 283.60	C 208
2	Rear bumper side retainers - L/R @ 65.50	
1	Rear end panel	349.80
1	Rear end panel garnish	
1	Rear floor board	
1	Rear floor tool tray	
1	Rear floor panel	
1	Rear fender - LH	
2	Rear fender inner trim boards - L/R @ 441.20	
1	Rear smart keyless antenna	
1	Rear smart keyless buzzer	

	Amount \$	
B1	931.60	✓
na	121.30	—
na	282.60	X
na	68.60	✓
na	563.20	let X
na	280.90	✓
na	311.60	✓
na	191.60	5061w
na	282.40	X
na	123.00	X
na	24.40	X
na	823.00	let
na	181.60	✓
na	712.20	✓
na	180.60	✓
na	173.20	let
na	567.20	let
na	131.00	✓
na	483.90	✓
na	155.60	✓
na	361.90	X
na	286.90	X
na	893.40	X
na	891.90	X
na	882.40	X
na	181.90	✓
na	190.60	✓
Sub-total	10,278.50	
Less 20%	2,055.70	
Total List	8,222.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle number: SMV1007E

Vehicle Made & Model: HONDA JAZZ

Special Nett Items

1 set Tailgate glass sealant
1 set Rear bumper clip
1 set Rear no. plate
1 Rear reverse camera

<i>Mr</i>	80.00	<i>4052</i>
<i>Mr</i>	50.00	<i>—</i>
<i>Dr</i>	65.00	<i>4552</i>
<i>Pu</i>	450.00	<i>X</i>
Total Special Nett	645.00	

Labour charges

To check rear electrical wiring
To remove, refix tailgate glass
Transfer and refix tailgate components to new tailgate
To respray undercoating
To respray painting and etc
Panel beating, cut, weld remove & replacing above parts

50.00	<i>201</i>
180.00	<i>1201</i>
150.00	<i>601</i>
120.00	<i>601</i>
1,200.00	<i>6001</i>
1,500.00	<i>7001</i>
Total Labour	3,200.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 12,067.80

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	226B
Vehicle Details	
Vehicle No.:	SMV1007E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Sep 2024
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.3 CVT
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	L13B15000984
Chassis No.:	JHMGK3850LS218212
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$16,663.00
Original Registration Date:	16 Sep 2020
First Registration Date:	16 Sep 2020
Transfer Count:	0
Actual ARF Paid:	\$6,663.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2030
PARF Rebate Amount:	\$4,997.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,000.00
COE Rebate Amount:	\$19,662.00
Total Rebate Amount:	\$24,659.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 26 Sep 2024

OK