



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

24 June 2024

Not Allowed in near
21/06/24
1/c #4600
7 days
Zhang Hanyu

REG NO.: SMH 2535 P
MAKE/MODEL: MITSUBISHI ATTRAGE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>NETT ITEMS</u>		
1	Rear windscreen moulding	\$ 17 105.00 X
1	Rear boot lid	\$ 725.00 ✓
1	Rear boot logo	\$ 48.00 ✓
1	Rear boot rubber	\$ 142.00 X
1	Rear taillamp -LH	\$ 420 485.00 ✓
1	Rear taillamp panel	\$ 185.00 X
1	Rear bumper	\$ 785.00 ✓
1	Rear bumper bracket	\$ 65.00 X
1	Rear bumper reinforcement	\$ 225.00 X
2	Rear bumper side retainers	\$ 42 97.00 ✓
1	Rear floor board panel top board	\$ 203.00 ✓
1	Rear end panel	\$ 448 558.00 ✓
1	Rear end panel inner garnish	\$ 69 145.00 ✓
1	Rear smart keyless sensor	\$ 101 186.00 ✓
1	Rear fender -LH	\$ 895.00 X
1	Rear fender air vent	\$ 48.00 X
1	Rear antenna sensor	\$ 95.00 ✓
		\$ 4,992.00
	Less 10%	\$ 499.20
		\$ 4,492.80

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$ 80.00 X
1	Rear bumper clip (1 set)	\$ 50.00 30
1	Rear bumper lower spoiler	\$ 750.00 ✓
1	Rear reverse sensor (1 set)	\$ 280.00 200
1	Rear fender inner shield clip (1 set)	\$ 45.00 X
		\$ 1,205.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 20
2	To remove and refit inner garnishes.	\$ 150.00 60
3	To remove and refit rear reverse sensor.	\$ 150.00 30
4	To transfer boot lid mechanism and wiring assembly.	\$ 80.00 50
5	To remove and refit fuel tank assembly with all attachments.	\$ 180.00 X
6	To remove and refit rear windscreen glass.	\$ 180.00 X
7	To apply undercoating.	\$ 180.00 50
8	Panel beating.	\$ 1,500.00 900
9	To re-spray painting on the affected areas.	\$ 1,400.00 1100
		\$ 3,900.00

GRAND TOTAL :

\$ 9,597.80

P 2936
102
2642.40
980
2210
5832.4
4665