



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com



Reference No.: 13092024

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 13.09.2024

Arabadjieva Elena Gueorguieva
61 Meyer Road #23-04
Singapore 437885.

Toyota Estima 2400cc

Supplementary Repair Cost for Vehicle Reg. No: SGS 3453 Z

1 Pc. Rear End Panel Lower Garnish	money broke	532.10	✓	286-93
1 Pc. Rear Left Fender Inner Garnish	money broke	1,280.00	✓	928.50
1 Pc. Rear Tailgate Antenna	money broke	531.00	✓	395.00

Total (Panels / Parts): **2,343.10 (SGD)**

1610-43

We shall be glad if you can forward the payment at your early convenience. 25% 1207.82

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

Payment Method

1. PAYNOW via UEN 39108900E
2. Bank Wire Transfer - (SGD Account)

Beneficiary/Company Name	Alfred Auto Services & Supplies
UEN no.	39108900E
Beneficiary's Bank Name	OCBC Bank
Account No.	620-453233-001
Bank Code	7339
Branch Code	620
Swift Code	OCBCSGSG

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.