

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 24.32098 Date: 08th Oct 2024

Our Ref: CS1/LAW24090500/Eqp3e2

M/s HSBC Life (Singapore) Pte Ltd

C/o Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SKC 7576M

INSURED VEHICLE: SMC 3791K ACCIDENT DATE: 12/10/2019

We thank you for your instruction on 24/09/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SKC 7576M from M/s Allin Automotive Appraisers.
- b) Singapore Accident Statement of Vehicles SKC 7576M and SMC 3791K.
- c) Final Repair Bill of SKC 7573M from M/s Sat (SG) Pte Ltd.
- d) Colour damaged vehicle photographs of SKC 7576M.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SKC 7576M Make & Model : BMW 318I

Chassis Number : WBAPF72080A793929

Year of Registration : 2018 Engine Capacity : 1995 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.