



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CS3/FCI22009129/Eny3e2-1 Date: 15/11/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PC 5189B	Veh. Inspected	FBS 8681H
Policy No.	D-22099590MFBP/1	Coverage (\$)	0.00
Claim No.	D22002645MFBP	Excess (\$)	0.00
Assign From	ESTHER LIM	Assign Date	11/11/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA FORZA	c.c	329
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MLHNF097XM5019388	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	140/70-14	BRIDGESTONE	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-15	BRIDGESTONE	4 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/08/2022	Inspection Date	16/09/2022
Survey held at	SPEEDWAY MOTOR PL 36 TOH GUAN ROAD EAST #01-32 ENTERPRISE HUB SINGAPORE 608580		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	