

Your Ref: TO BE ADVISED  
Our Ref: 2024-4879/RC/PC



21/10/2024

c/o LKK Auto Consultants Pte Ltd  
Singapore

**SBS Transit Ltd**  
205 Braddell Road Singapore 579701

Mainline +65 6284 8866  
Facsimile +65 6287 0311

[www.sbstransit.com.sg](http://www.sbstransit.com.sg)

Company Registration No: 199206653M

Dear Ms Hsiao Tong,

**ACCIDENT INVOLVING SMB3161J & MID 21812 ON 27/09/2024**

We understand that you are the handler of vehicle no. MID 21812, which was involved in the above accident with our bus no. SMB3161J.

We are of the opinion that the accident was caused by the negligent driving of the driver. As a result of the accident, we have been put to loss and expense as follows:

Cost of repair	\$	9,361.35	
Loss of use	\$	3,672.90	( 408.10 x 9.00 )
Total	\$	13,034.25	

We enclose the following supporting documents: -

- |   |  |
|---|--|
| <input type="checkbox"/> A copy of the GIA/ Police Report of SMB3161J | <input type="checkbox"/> Survey Report & Survey Bill |
| <input type="checkbox"/> A copy of the Certification for Bus Repair   | <input type="checkbox"/> GIA/LTA Search fee          |
| <input type="checkbox"/> Coloured Photographs / Scene Photographs     | <input type="checkbox"/> Others, _____               |


We trust that you will settle this claim promptly to avert legal costs and interest charges. To this end, please treat this as notice in accordance with the protocol for Non-Injury Motor Accident litigation.

We look forward to hearing from you early in order to resolve this matter amicably at minimum cost to you.

Yours faithfully,

Priscilla Chan  
Group Claims Unit  
DID: 63837026  
Email: [chanfl@sbstransit.com.sg](mailto:chanfl@sbstransit.com.sg)

**Please scan QR code to read SBS Transit Ltd Data Protection Policy:**



The information contained in these documents may be privileged and confidential and is intended for the exclusive use of the addressee designated above. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error, please notify the sender immediately.

THE MESSAGE IS CONFIDENTIAL. ANY UNAUTHORISED DISCLOSURE, USE OR DISSEMINATION, EITHER WHOLE OR PARTIAL, IS PROHIBITED.



**HxGN EAM**

## Accident Report

User

VELMURUGANS@SBSTRANSIT.COM.SG

Report Created

Oct 21, 2024

## Certificate of Bus Repair

Depot	SE	Bus No	SMB3161J
Driver	79368	Accident Date	Sep 27, 2024
Work Order No	1536073	Case No / AR No	22907 / AR-2024-5319

Date IN Sep 27, 2024

Date Out

Oct 7, 2024

Registration Date	Model/Manufacturer	Chassis No.
Dec 1, 2015	MAN A22 EU5, SD, AC, 2 Axle	WMAA22ZZXF7002773

Stock Code	Description	Quantity	Total Material Cost (S\$)
30400032 N	DOOR.RADIATOR .SIDE PANEL N	-1	-\$874.00
30401097 N	RADIATOR GRILL.A22.E5 N	1	\$874.00
30117300 N	REAR WINDSCREEN N	1	\$495.00
30117340 N	GLASS.SIDE.NO 6.O/S N	1	\$348.00
90082378 N	STKR THANK YOU FOR GIVING WAY N	1	\$2.50
30400032 N	DOOR.RADIATOR .SIDE PANEL N	1	\$874.00
30400033 N	DOOR.AIR INTAKE .SIDE PANEL N	1	\$127.50
30541771 N	LED.SIGNAL LAMP.RR.LH/RH N	1	\$308.43
43311001 N	INSCRIPTION."3D".MAN LOGO.RR N	1	\$62.31
30400245 N	COVER.REAR LAMP.O/S N	1	\$339.00
30400302 N	HINGE.RADIATOR DOOR N	2	\$60.00
30541770 N	LED.TAIL/STOP LAMP.RR.LH/RH N	2	\$641.30
30400451 N	RADIATOR DOOR FRAME.E6.A22 N	1	\$250.00

TOTAL FOR PARTS		S\$ 3,508.04
S/N	Labour / Spray Painting / Contractor Cost	Amount

1	Workshop Labour	S\$	188.00
2	Contractor's Repair Charges	S\$	3,180.00
<b>TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST</b>		<b>S\$</b>	<b>3,368.00</b>
<b>Repair cost of Advertisement / Livery</b>		<b>S\$</b>	<b>325.00</b>
<b>TOTAL DAMAGE</b>		<b>S\$</b>	<b>7,201.04</b>
<b>Overheads</b>		<b>S\$</b>	<b>2,160.31</b>
<b>Towing Charges</b>		<b>S\$</b>	<b>0.00</b>
<b>Repair Period : 9.00 Days</b>		<b>Loss of Use</b>	<b>S\$ 3,672.90</b>
<b>TOTAL LOSS</b>		<b>S\$</b>	<b>13,034.25</b>