



MOTORCYCLE ACCESSORIES | SERVICE CENTRE MCDIFICATION | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO.

: 47817

LONPAC INSURANCE BHD 100 BEACH ROAD #19-00 SHAW TOWER SINGAPORE 189702

ATTN: LONPAC INSURANCE BHD

DATE

: 30/09/2024

CLAIM NO.

: 12603

POLICY NO. : MC/01230958/01

FROM

: STEPHANIE

VEHICLE NO.

Customer:

: FBT9863M

MAKE/MODEL

: K.T.M / 1290 SUPER ADVE

(Page 1 of 7)

<u>S/N</u> 1	Description AIR DUCT INTAKE RH - (REPORTED BY MECHANIC)	Action REPLACE	<u>Qty</u> 1.00	<u>Unit Price</u> \$94.00	<u>Amount</u> 94.00
2	AIR INTAKE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	155.00
3	AXLE FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$280.00	280.00
4	BODY ALIGNMENT - (REPORTED BY MECHANIC)	Repair	1.00	\$1,550.00	1,550.00
5	BOLT M5X14 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$7.00	14.00
6	BOLT STEERING HEAD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
7	BRACKET FUEL HOSE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
8	BRACKET UNDER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,085.00	1,085.00
9	BRAKE FLUID DOT5.1 0,25L P/N: 63833 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00







<u>S/N</u> 10	Description CAMERA (V_SYS) M6 (WIFI VERSION) P/N: 56377 - (REPORTED BY MECHANIC)	Action REPLACE	<u>Qty</u> 1.00	<u>Unit Price</u> \$388.00	<u>Amount</u> 388.00
11	CLIP EXHAUST 60MM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
12	COLLAR SCREW - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	11.00
13	COMPARTMENT STORAGE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00
14	COVER DASHBOARD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00
15	COVER ENGINE (R&G) CASE(RH) KTM ADVENTURE P/N: 50757	REPLACE	1.00	\$232.00	232.00
16	- (REPORTED BY MECHANIC) COVER FUEL TANK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,008.00	1,008.00
17	COVER HEADLAMP LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$218.00	218.00
18	COVER HEADLAMP RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$218.00	218.00
19	COVER HEADLAMP UNDER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00
20	COVER HEADLIGHT MASK HOLDER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$44.00	88.00
21	COVER HORN FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$67.00	67.00
22	COVER INNER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	164.00
23	COVER INNER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	164.00
24	COVER INTAKE DUCT LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00
25	COVER INTAKE DUCT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$85.00	85.00







<u>S/N</u> 26	<u>Description</u> COVER INTAKE PORT FOR LH - (REPORTED BY MECHANIC)	<u>Action</u> REPLACE	<u>Qty</u> 1.00	Unit Price \$55.00	<u>Amount</u> 55.00
27	COVER INTAKE PORT FOR RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00
28	COVER MUFFLER PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00
29	COVER SIDE FRONT UPPER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	233.00
30	COVER SIDE FRONT UPPER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	233.00
31	COVER SPOILER LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,024.00	1,024.00
32	COVER SPOILER RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,024.00	1,024.00
33	COVERBUSHING CHAIN PROTECTION - (REPORTED BY MECHANIC)	REPLACE	4.00	\$17.00	68.00
34	CRASHBAR SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$961.00	961.00
35	CROWN HANDLE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$876.00	876.00
36	DAMPER STEERING - (REPORTED BY MECHANIC)	REPLACE	1.00	\$651.00	651.00
37	DAMPER STEERING CLAMP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$202.00	202.00
38	EXHAUST MANIFOLD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3,410.00	3,410.00
39	EXHAUST PIPE FLANGE GASKET P/N: 63825	REPLACE	2.00	\$55.00	110.00
40	- (REPORTED BY MECHANIC)FOOTREST FRONT RH- (REPORTED BY MECHANIC)	REPLACE	1.00	\$109.00	109.00
41	FORK ASSY FRONT SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6,635.00	6,635.00







Quote	alion 1905 47017				, 9 ,
<u>S/N</u> 42	Description FORK FRONT SLIDER - (REPORTED BY MECHANIC)	Action REPLACE	<u>Qty</u> 1.00	<u>Unit Price</u> \$141.00	<u>Amount</u> 141.00
43	GASKET INTAKE DUCT - (REPORTED BY MECHANIC)	REPLACE	2.00	\$28.00	56.00
44	HANDGUARD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$226.00	226.00
45	HANDLEBAR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$550.00	550.00
46	HANDLEBAR RISER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$107.00	214.00
47	HEADLAMP ADJUSTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	63.00
48	HEADLAMP ADJUSTER THUMBWHEEL - (REPORTED BY MECHANIC)	REPLACE	1.00	\$40.00	40.00
49	HEADLAMP ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3,333.00	3,333.00
50	HEADLAMP PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$0.00	0.00
51	HEADLAMP SUPPORT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$75.00	75.00
52	HEADLIGHT MASK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$195.00	195.00
53	HEADLIGHT SUPPORT TOP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
54	HH COLLAR SCREW M8X30 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$11.00	22.00
55	HORN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$122.00	122.00
56	IGNITION KEY PROGRAMMING AT KTM AGENT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$745.00	745.00







Quota	ation nos 47017				(1 ago o o 17)
<u>S/N</u> 57	Description LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND	Action Supply/Install	<u>Qty</u> 50.00	Unit Price \$85.00	<u>Amount</u> 4,250.00
58	INSTALLATION OF PARTS. LAMP SIGNAL FRONT RH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$148.00	148.00
59	LOCKSET RACE-ON - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,635.00	2,635.00
60	MANIFOLD GASKET P/N: 63849 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00
61	MANIFOLD GASKET 60MM P/N: 63852 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	63.00
62	MASTER CYLINDER PUMP BRAKE RH ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,109.00	1,109.00
63	METER ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$6,665.00	6,665.00
64	MIRROR SET - (REPORTED BY MECHANIC)	REPLACE	2.00	\$256.00	512.00
65	MUDGUARD FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$296.00	296.00
66	MUFFLER (LEOVINCE) - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,140.00	2,140.00
67	MUFFLER PROTECTOR - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
68	NUT SPRING M5 - (REPORTED BY MECHANIC)	REPLACE	3.00	\$11.00	33.00
69	OBU TYPE B (12V) NEW P/N: 82490 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$341.00	341.00
70	O-RING VITON P/N: 55505 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$17.00	17.00
71	PEDAL BRAKE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$326.00	326.00







Quot	alloff 1905 47 0 17				(,9 ,
<u>S/N</u> 72	Description PLATE DISC BRAKE FRONT D=320X4.5 - (REPORTED BY MECHANIC)	<u>Action</u> REPLACE	<u>Qty</u> 1.00	<u>Unit Price</u> \$683.00	<u>Amount</u> 683.00
73	POWER SOCKET COMPLETE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	132.00
74	RIM FRONT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,170.00	2,170.00
75	SCREW M5X12 - (REPORTED BY MECHANIC)	REPLACE	11.00	\$11.00	121.00
76	SCREW M5X17 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$11.00	11.00
77	SCREW M6X18 8.8 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$13.00	52.00
78	STAND MAIN - (REPORTED BY MECHANIC)	REPLACE	1.00	\$869.00	869.00
79	STEERING CONE SET - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00
80	STICKER FORK - (REPORTED BY MECHANIC)	REPLACE	1.00	\$71.00	71.00
81	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$30.00	30.00
82	- (REPORTED BY MECHANIC)STICKER SET- (REPORTED BY MECHANIC)	REPLACE	1.00	\$590.00	590.00
83	SWING ARM SLIDER MOTOVATION - (REPORTED BY MECHANIC)	REPLACE	1.00	\$233.00	233.00
84	SWINGARM ASSY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4,185.00	4,185.00
85	SWINGARM KIT - (REPORTED BY MECHANIC)	REPLACE	1.00	\$249.00	249.00
86	SWITCH HANDLE LH - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,395.00	1,395.00









(Page 7 of 7)

Quotation Nos.: 47817

S/N	Description	<u>Action</u>	<u>Qty</u>	Unit Price	<u>Amount</u>
87	TYRE PRESSURE SENSOR P/N: 81401 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$427.00	427.00
88	VALVE RIM - (REPORTED BY MECHANIC)	REPLACE	1.00	\$91.00	91.00
89	WASHER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
90	WASHER - (REPORTED BY MECHANIC)	REPLACE	2.00	\$5.00	10.00
91	WASHER THRUST 25X35X0.5 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$5.00	5.00
92	WINDSHIELD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	388.00
93	WIRE HARNESS - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,790.00	2,790.00
		SUB TOTAL GST @ 9 %			\$61,690.00 \$5,552.10
		GRAND TOTAL (SG	D)	pares	\$67,242.10

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



STEPHANIE

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.







ERT MO: 2002-1-6163 ESO 9661 : 2615



CEV/VES Rebate Utilised Amount:

Vehicle Details

CO2 Emission:

Make/Model Vehicle No. K.T.M. / 1290 ADVENTURE S FBT9863M Vehicle Type: Vehicle Attachment 1: P00 - Passenger Motorcycle/Autocycle No Attachment /Moped Chassis No.: Vehicle Scheme: VBKV79402JM992280 Normal Propellant: Engine No.: 860723423 Petrol Engine Capacity: Motor No.: 1301 cc Maximum Power Output: Power Rating: Unladen Weight: Maximum Laden Weight: 245 kg 460 kg Original Registration Date: Year Of Manufacture: 06 Jul 2018 2018 COE Category: Lifespan Expiry Date: D - Motorcycle COE Expiry Date: Quota Premium: 05 Jul 2028 \$6,514.00 PARF Eligibility Expiry Date: Road Tax Expiry Date: 05 Jan 2025 Intended Transfer Date: Inspection Due Date: 24 Sep 2024 05 Jul 2025

SB0F249N0004 / Ban Hock Hin Co Pte Ltd ENTRY DATE & TIME: 23/09/2024 17:50 (SGT) SUBMITTED BY: Gan Lay Peng VERSION: 1 (23/09/2024 17:50 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

23/09/2024 17:50 (SGT) Date of First Submission Both Policyholder and Actual Driver 03/09/2024 15:45 (SGT) Date of Accident Exact Location of Accident Singapore Additional Location Information MANDAI ROAD Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Ktm

Vehicle Registration Number FBT9863M

Manufacturer

INSURED/POLICYHOLDER

ZAINAL ABIDIN BIN NAHWAN Name Of Registered Owner SXXXX150G Email Address JAYNAL723@GMAIL.COM (Phone) +65-82986559 Mobile Phone No Alternative Phone No

VEHICLE PARTICULARS

Model 1290 Variant Adventure S Exact purpose for which vehicle was being used at time of Private use accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Motorcycle Vehicle Category Transmission Manual 1290 Vehicle Fuel First Regisration Date Chassis no Effective Date/Time of Ownership

INSURANCE COMPANY

Direct Asia Insurance (Singapore) Pte Ltd Name of Insurance Company Policy Number / Cover Note Number MC/01230958/01

DRIVER

Name of Driver	ZAINAL ABIDIN BIN NAHWAN
NRIC No	SXXXX150G
Date Of Birth	05/09/1972
Occupation	Outdoor
Driving Pass Date	28/05/2002
Driving License Pass Class	2
Driving License Validity	Valid
Driving experience	22 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82986559
Alt. Phone Number	- LAVALAL 700 COMAIL COM
Email Address Address	JAYNAL723@GMAIL.COM BLK 228 YISHUN ST 21 #07-484
Address Address complement	DLK 220 TISHUN ST 21 #07-404
Postcode	760228
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
***************************************	-
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Hit by fallen tree / Other objects
Weather Conditions	Clear
Road Surface	Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	No 1
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID Translator's phone number	-
Translator's email	-
Original language used in the statement	
Original language used in the statement	-
PASSENGER 1	
Name	NORDALINA BINTE JUMAHAT
Gender	Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-
CIRCUMSTANCES OF ACCIDENT	
GINGUINOTAINOLO OL MOODELNI	
Refer to Sketch Plan	

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XD9447E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ZAINAL ABIDIN BIN NAHWAN
Gender	Male
Phone No	(Phone) +65-82986559
Address	•
Address Complement	-
Post Code	•
Approximate Age Years Old	-
Injuries Sustained	Open Fracture Left Wrist, Closed Fracture Right Wrist, Fore head left open wound, spinal fracture and broken tooth.
Injured person in which vehicle?	-
Were seat belts worn?	No
Was this injured conveyed to hospital by ambulance?	Yes
INJURED 2	
Name of injured person	NORDALINA BINTE JUMAHAT
Gender	Female
Phone No	(Phone) +65-82026000
Address	-
Address Complement	_
Post Code	_
, 44	-
Approximate Age Years Old	Fracture right ankle, right shoulder bruises and neck whiplash,
Injuries Sustained	bruising on left ribs and shoulder.
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

WITNESS DETAILS

WITNESS 1

Name		Syukor
Phone	201104000000000000000000000000000000000	(Phone) +65-93369461
Email		-

Describe Circ	scribe Circumstance of the Accident									
βı	tei	10	Report	No.	T/200	4091	11/710	4.		Alg English Tag Art 20 A
		en e como que literar en constitución de la constit	renga ay ah	destruit Nation (volume establisme destrict	ومرود والمرادة والمرا	\$ 15 may \$ 25 declaration of South Association for any the antibon New York	والمرافقة		nakanni di nakanni libera (148) eti minera di errantidi	والمعشمة والمحمودة والمحمدة والمحمدة والمحمد والمشارعة والمحمدة وا
	-Sellect Cont		enny waspinata was a sa Mahahi						eneralli sassara kalifoli inalian kili arankilani bena bela er	ود بایده و استانه مشاهده و در
	umanan ladi sedimente distribi							ar mail arm a communication with the comment of the		
		name of the answer word default for the	enterview (and completely apply supply dependent defection construction)	d Charles and the control of the con	era grandi unterripto de de la dissociação de la	gggggggathinad o're dellandradod dordalishe i dd h.		ورسيد والمستوم والمستومة والمراور والمراورة وا		
<u></u>		oodenist iestimin luvide	nna tanàna dia dia mandridra dia dia dia dia dia dia dia dia dia di	and players a reconstruction of the contract o		operation and the second and the sec				
	our-chromes		outer outside to have been been been been been been been be	and the second s			20000000000000000000000000000000000000			a y ser sang ang ang ang ang ang ang ang ang ang
	I-476.014					e-contra con des disselledes médicies de la				
alaintaman tarailainte a ^{la} 1910 (see 1910 et 1918) 1970 estatel e e		nanga daga daga daga baran daga daga daga daga daga daga daga da			Lands remarked the common of the Artificial recentrality to	ennak pakipana kamana sababa saba - i	opennym z kazy na miene konstrukciów bien b			
	<u>. A. A.</u>									
										والمناف المناف والمنافضة في المنافضة والمنافضة
		g et anno anno anno anno anno anno anno ann	ASSIA all throughertentiaete-stantaett/statety-st	ganing at convention that have been		12 natura (1882 1888 1884 1884 1884 1884 1884 1884	and planting the second sec	ome de designe de la collectiva de la compansa de la Secución de la collectiva de la collec	ninalished (Spell) of Anthony in the section is the Spell	tambo maranda (taban dan kalan dan dan dan dan dan dan dan dan dan d
A										
									on also appropriate to proper and the temporary of temporary of temporary of temporary of temporary of temporary of temporary	
		namental and a second second and a second		agains and second or the control of						
and the second limit to the second limit to the latest the second limit to the second										
					algori filosopo (s. 1904) por filosoficial e epitalis al constituidad de la constituidad de la constituidad de En constituidad de la constituidad					
		manufacture and constitute of \$1.5% \$1.5%	142-1445-Armen Asama II.A-miriad		gy o given family and a common the side and distribute	nage, and also transported that the elaboration directions		_11.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1		والمناف والمارات والمرافعة المرافعة الم
e regional construction in the second second second development of the PROVING					escenciolistica de escencio de la messa parte de escencio de la messa parte de escencio de la messa parte de e		NACH TERRETARING THE STREET OF			

Declaration

I/We declare the foregoing particulars are true in every respect.

23/9/24 Policyholder's Signature / Oale & Time

Oriver's Signature (4 driver is not the policyholder) / Date

Gan Lay Ping Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

2

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8, Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC(II) card)

Sketch Plan



generator

1



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



3 of 3

Report No. T/20240911/7104

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 11/09/2024 17:14
Officer In Charge Of Case: TP / TPIB / MUHAMMAD AZHAR BIN ANUAR Contact No.: 96191462	Classification Of Case:

NP168



T/20240911/7104

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

2 of 3 Report No. T/20240911/7104

CONTINUATION OF REPORT

Any Pedestrian In	volved; No				
No. of Pedestrians	; Injured: NIL	Use of Pedestrian Crossing: NA			
Pillion					
Name	NORDALINA BINTE JUMAHAT		ID No.		S7831173H
Related Vehicle	FBT9863M (Motorcycle)		Contact No.		82026000
Hospital/Olinic	KHOO TECK PUAT HOSPITAL	german gegerge. La grad allerd in chloride del grad difference que general del grad	Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL
Date Treatment	03/09/2024	Date Disch	scharge 07/09		/2024
No. of Days grant	ed Medical Leave (MC) 11	Degree of I	of Injury Serious		us
Rider					
Name	ZAINAL ABIDIN BIN NAHWAN		ID No	·	S7231150G
Related Vehicle	F8T9863M (Motorcycle)	<mark>aga-aga-aga-aga-aga-aga-aga-aga-aga-aga</mark>	Contact No.		82986559
Hospital/Clinic	NIL		Class Drivin Licen Expin	g	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch	ı arge	NIL	
No. of Days grant	ed Medical Leave (MC) NIL	Degree of I	njury	NIL	

Brief Details.

Lwish to refer to my earlier Traffic Accident report no. T/20240905/7055, made on 5 sept 2024 at 13.45pm.

Twish to state that the lorry that caused the big generator to roll down and hit my motorcycle is XD9447E. This lorry was parked in the construction site on the other side of the road that negligently caused the big generator that was on this lorry to fall down and rolled across the road to my lane and violently collided into my motorcycle no. FBT9863M.

The big generator rolled down very fast because it was a slope and i had no time to react which resulted in the serious accident with my motorcycle causing me and my wife (pillion), Nordalina Binte Jumahat to fall off the bike and suffered serious injuries.

Land my wife were later conveyed by ambulance to KTPH for medical treatment. I was given 9 days of Hospitalization Leave and my wife was given 11 days of Hospitalization leave. I am still warded in Yishun Community hospital for rehabilitation. I suffered head injuries, open fracture of the left wrist, close fracture Of the right fracture, broken tooth, stitches above my right eye, stitches below my lips and fracture C10 vertebrae and other injuries. My wife suffered a fractured right ankle and bruises on some parts of her body.

Lenclosed the Hospitalization Leave And Discharge Summary of me and my wife herein.

We wish to claim for our serious injuries and other consequencial losses frm the insurance company of the motorlorry.



T/20240911/7104

Date of Expiry:

1 of 3 Report No. T/20240911/7104

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

REPORT OF A TRAFFIC ACCIDENT

Occupation: Assistant mechanical engineer

Tel No: 65470000

Race: Boyanese

Date/Time Report Made: 11/09/2024 17:14			Vide Report No.: Station Diary No.: L/20240903/0081				
Informan	it's Particula	ns					
	Informant: ABIDIN BIN	NAHWAN	Address: 228 YISHUN STREET 2	1 #07-484 SINGAPORE 760228			
ID Type / ID No.: NRIC NO / S7231150G			Contact No.: Home/Office: Mobile: 82986559				
Nationality: SINGAPORE CITIZEN		Email: JAYNAL723@GMAIL.COM					
Sex: Male	Age: 52	Date of Birth: 05/09/1972	Type of Informant: Rider				

Driving Licence Information:

Language: English

Class:

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 03/09/2024 16:00	Type of Location Straight Road	
Lecation:	1		and the second s		
MANDAI ROAD					
Weather:		Road Surface:			
regular.		Dry			
Traffic Flow:		Traffic Control:		Traffic Volume:	
Traffic Flow:			3		
Traffic Flow: One Way		Not Controlled	Lig	ht	

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBT9863M	Motorcycle	KTM	1290 ADVENTURE S	Black		
XD9447E	Lorry	and the same of th		N TO THE PERSON NAMED IN COLUMN NAMED IN COLUM		0

Details of Vehicle Insurance							
Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date			
FBT9863M	DIRECT ASIA INSURANCE (SINGAPORE)	MC/01230958/01	13/07/2023	05/07/2025			
	PTE, LTD.						