



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581	Ref: Date: Code:	CS/FCI24100002/Kvp3e2 01/10/2024 FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2381B	Veh. Inspected	SGU 6989P
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24008561MFCT	Excess	\$0.00
Assign From	HARMINDER	Assign Date	30/09/2024
2. Vehicle Details			
Make & Model	MITSUBISHI ATTRAGE (A)	C.C	1193
Engine No.	3A92UDS1300	Year of Reg.	14/02/2017
Chassis No.	MMBSTA13AHH004341	Colour	METALLIC GREY
Odometer	102398 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	185/55R15	DUNLOP	4
L/H Front Tyre	185/55R15	DUNLOP	4
R/H Rear Tyre	185/55R15	DUNLOP	4
L/H Rear Tyre	185/55R15	DUNLOP	4
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/09/2024	Inspection Date	30/09/2024
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days			