



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWERSINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24100009/Avh3m4(N) Date: 24/01/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKF 997L	Veh. Inspected	SNP 9088M
	Policy No.		Coverage (\$)	0.00
	Claim No.	IVS24/1852	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	30/09/2024
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA180 COUPE	c.c	1332
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	W1K1183842N245636	Colour	GREY
	Odometer	44188 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/45R18	GOODYEAR	6 mm
	L/H Front Tyre	225/45R18	GOODYEAR	6 mm
	R/H Rear Tyre	225/45R18	GOODYEAR	6 mm
	L/H Rear Tyre	225/45R18	GOODYEAR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/09/2024	Inspection Date	28/10/2024
	Survey held at	XIN YUN AUTO PTE LTD BLK 8 KAKI BUKIT AVENUE 4 #05-23 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)REGISTRATION DATE: 13 SEP 2021 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	