



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

MS First Capital Insurance Ltd

Date : 27/09/2024

ESTIMATE

Attn : Motor Claim Department

Vehicle Number : SLQ5703R
Make & Model : HONDA VEZEL HYBIRD
Chassis Number : RU31226100
Registration Date : 20/07/2017
Date Of Accident : 26/09/2024 22:20
3rd Party Vehicle No. : SMB1481Z

PARTS DIScription		QTY	UNIT PRICE		LIST PRICE	
				S\$		S\$
1	HEADLAMP LH (NON-LED) ? Xan	1	\$	897.56	\$	897.56 X
2	HEAD LAMP UPPER BRACKET LH ? Xan	1	\$	89.00	\$	89.00 X
3	HEADLAMP LOWER BRACKET LH ? Xan	1	\$	55.00	\$	55.00 X
4	FRONT BUMPER de/	1	\$	798.00	\$	798.00 765
5	FRONT BUMPER SIDE RETAINER LH ? Xan	1	\$	68.00	\$	68.00 X
6	FRONT FENDER LH refer 107390	1	\$	830.00	\$	830.00 XR
7	FRONT FENDER 'HYBIRD' EMBLEM LH m/ 20%	1	\$	86.00	\$	86.00 58.90
8	FRONT FENDER INNER SHIELD LH Xan	1	\$	228.60	\$	228.60 X
9	FRONT WHEEL ARCH GARNISH LH sc/ 85912	1	\$	298.20	\$	298.20 250
10	FRONT KNUCKLE ARM LH ? Xan	1	\$	689.00	\$	689.00 X
11	FRONT KNUCKLE BEARING LH ? Xan	1	\$	107.50	\$	107.50 X
12	FRONT SHOCK ABSORBER LH Xan	1	\$	384.50	\$	384.50 X
13	FRONT STABILIZER LINK LH Xan	1	\$	210.00	\$	210.00 X
LIST TOTAL S\$:				\$	4,741.36	
20.00% DISCOUNT S\$:				\$	948.27	
				\$	3,793.09	

SPECIAL NETT		QTY	UNIT PRICE		AMOUNT	
				S\$		S\$
1	FRONT BUMPER CLIPS SET m/	1	\$	50.00	\$	50.00 30
2	FRONT FENDER INNER LINER CLIPS SET Xan 596	1	\$	40.00	\$	40.00 X
3	FRONT WHEEL ARCH GARNISH CLIPS SET m/	1	\$	40.00	\$	40.00 30
4	WHEEL CAP m/	1	\$	90.00	\$	90.00 /
5	WHEEL RIM 4/	1	\$	320.00	\$	320.00 250
6	WHEEL TYRE 215/60R16 cut/ 70%	1	\$	280.00	\$	280.00 196
SPECIAL NETT TOTAL S\$:				\$	820.00	

LABOUR CHARGES

- | | | | |
|---|---|----|---------------------------------|
| 1 | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; REPLACE DAMAGED PARTS AND COMPONENTS | \$ | 600.00 400 |
| 2 | TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED AND AFFECTED AREA. | \$ | 600.00 400 |
| 3 | TO REMOVE AND RE-FIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS | \$ | 80.00 XM |
| 4 | WHEEL ALIGNMENT | \$ | <u>960</u> 120.00 60 |
| 5 | DISMENTLE AND REPLACE FRONT LHS UNDER-CARRIAGE COMPONENTS. | \$ | 180.00 100 |
| 6 | TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS | \$ | 80.00 XM |

LABOUR TOTAL S\$: \$ 1,660.00

TOTAL S\$: \$ 6,273.09

9% GST: \$ 501.85

GRAND TOTAL S\$: \$ 6,774.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
 Hs 70010068
 4 days
 4/s
 01/10/24
 Reg after
 repair
 859.12
 596.00
 960.00
2415.12
 20%
 1932.69
 Hs-\$1900
 4 days