



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100018/Eqp3m4
(BUDGET DIRECT INSURANCE)	Date:	21/10/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 5055M	Veh. Inspected	SMP 4964D
Policy No.	P10446947R04	Coverage	0
Claim No.	C10031965/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	01/10/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS PLUS (AUTO)	C.C	1798
Engine No.	2ZR0E70887	Year of Reg.	27/09/2019
Chassis No.	JTDZS3EU40J049968	Colour	WHITE
Odometer	436679 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	SAILUN	5
L/H Front Tyre	205/60R16	SAILUN	5
R/H Rear Tyre	205/60R16	SAILUN	5
L/H Rear Tyre	205/60R16	SAILUN	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/09/2024	Inspection Date	01/10/2024
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days