

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	// IS LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24100019/Kvh3e2	
	ONE RAFFLES QU SINGAPORE 0485	AY #25-01 NORTH TOWER	Date:	11/10/2024	
	ON ONE OTHER		Code:	LIP	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMZ 489H	Veh. Inspected	SJP 940J	
	Policy No.	-	Coverage	0	
	Claim No.	AVS24/3033	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	01/10/2024	
2. Vehicle Details					
	Make & Model	TOYOTA VIOS (A)	C.C	1497	
	Engine No.	1NZX874132	Year of Reg.	11/03/2009	
	Chassis No.	MR053HY9305103656	Colour	METALLIC GREY	
	Odometer	297559 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195/55R15	MICHELIN	9	
	L/H Front Tyre	195/55R15	MICHELIN	9	
	R/H Rear Tyre	195/55R15	MICHELIN	9	
	L/H Rear Tyre	195/55R15	MICHELIN	9	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	. General Information				
	Accident Date	•			
	Survey held at GUAN MOTOR WORKS - 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721				
	5a. Remarks				
5a.					
A) T		AS CONDUCTED ON A"WITHOUT PF O YOUR INSTRUCTIONS, WE HAVE I		REPAIRS.	

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days