

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. : SAC2401056

INV Date : 18-10-2024

Reference CS3/III24100022/Tnp3m4

Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SNP 9291S
Insured Veh. GBC 7258M
Claim No. MFL2024D0011800
Policy No. D20MFL0000131_04
Accident Date 29/09/2024
Inspection Date 01/10/2024

Description	Amount
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	170.00
- First Inspection 01.10.2024 06.07pm	0.00
Merimen Fee	12.00
Sub-Total	182.00
GST (9%)	16.38
Grand Total	198.38

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML
