Our Ref

: SNP1934Z / TP#2652

Your Ref

: GBK5804H / CD/CTI24100030/Kpa3

WITHOUT PREJUDICE

Date: 20th January 2025

### CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Attention: Motor Claims Department

# ACCIDENT INVOLVING SNP1934Z & GBK5804H ON 27/09/2024 ALONG PASIR RIS CENTRAL

We refer to the above captioned.

We are claiming the below followings:

- Cost of Repair (incl. of GST)	S\$	15,507.26
---------------------------------	-----	-----------

- Loss of Rental S\$ 1,900.00 (\$190.00 X 10 Days)

27.25

- LTA / GIA Search Fee S\$

**Grand Total S\$ 17,434.51** 

If you have any enquiries, please contact our representative, Mr Joseph at 6481-1522 or email joseph@ow.sg

All payment is to be issued direct to **Optima Werkz Pte Ltd**.

Your prompt attention is most grateful and look forward to your speedy settlement.

Yours faithfully

OPTIMA WERKZ PTE LTD

Encl.

This is a computer generated printout and no signature is required.

# **Optima Werkz Pte Ltd**

10 Ang Mo Kio Industrial Park 2A #01-05/06, Singapore 568047 Tel: (+65) 6481 1522 Co Reg & GST No: 201212455W

#### **TAX INVOICE**

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Tel: 63896116 Fax: 62221033 INV NO.

: 322303658

INVOICE DATE

: 16/01/2025

REF

: TP#2652

VEH NO.

: SNP1934Z

MAKE

: TOYOTA

CAR MODEL

: ALPHARD HYBRID

**CURRENT MILEAGE:** 

ADVISOR : NG WEI HAO, JONATHAN

TERMS

: COD MECHANIC

DESCRIPTION	QTY	UOM	Tax Code	U/P SGD	AMT SGD
REAR BOOT	1	PCS	SR	2,100.00	2,100.00
RR WINDSCREEN MOULDING	1	PCS	SR	127.50	127.50
RR BOOTLID EMBLEM (HEV)	1	PCS	SR	75.75	75.75
RR BOOT LID INNER TRIM BOARD	1	PCS	SR	1,162.50	1,162.50
RR BOOTLID LOCK ASSY	1	PCS	SR	831.00	831.00
RR BOOTLID ELECTRIC STRUT - LH & RH	1	PCS	SR	2,100.00	2,100.00
RR BOOTLID SENSOR ASSY - LH & RH	1	PCS	SR	1,830.00	1,830.00
RR WEATHERSTRIP	1	PCS	SR	360.75	360.75
RR BUMPER	1	PCS	SR	649.50	649.50
REAR BUMPER ULTRASONIC SENSOR - CTR LH & RH	1	PCS	SR	315.08	315.08
RR END PANEL	1	PCS	SR	1,065.00	1,065.00
RR END PANEL BTM TRIM PANEL	1	PCS	SR	155.25	155.25
RR BOOTLID SUBWOOFER	1	PCS	SR	1,614.53	1,614.52
RR WINDSCREEN SEALANT	1	PCS	SR	40.00	40.00
RR BUMPER LOWER CHROME STRIPS - 1 SET	1	PCS	SR	180.00	180.00
LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REFIX RR AFFECTED AREAS	1	JOB	SR	600.00	600.00
TO PERFORM WIRING CHECKS ON ELECTRICAL SYSTEMS	1	JOB	SR	20.00	20.00
LABOUR CHARGES TO REMOVE, PUTTY, REPAIR, SAND & RESPRAY AFFECTED AREAS	1	JOB	SR	660.00	660.00
LABOUR CHARGES TO REMOVE, REPLACE & REFIX BUMPER SENSORS	1	JOB	SR	30.00	30.00
LABOUR CHARGES TO REMOVE, REPLACE & REINSTALL BOOTLID INNER MECHANISM	1	JOB	SR	30.00	30.00
TO PERFORM ADAS CHECKS, CALIBRATION & PROGRAMMING	1	JOB	SR	180.00	180.00
LABOUR CHARGES TO REMOVE, REFIX & REPLACE RR WINDSCREEN	1	JOB	SR	100.00	100.00

## **Optima Werkz Pte Ltd**

10 Ang Mo Kio Industrial Park 2A #01-05/06, Singapore 568047 Tel: (+65) 6481 1522 Co Reg & GST No: 201212455W

#### TAX INVOICE

To: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

INV NO. INVOICE DATE : 322303658

: 16/01/2025

REF

: TP#2652 : SNP1934Z

VEH NO.

MAKE

: TOYOTA

Tax

CAR MODEL

: ALPHARD HYBRID

**CURRENT MILEAGE:** 

ADVISOR

: NG WEI HAO, JONATHAN

**TERMS** 

: COD

**MECHANIC** 

DESCRIPTION

3 ANSON ROAD

Tel: 63896116

Fax: 62221033

SINGAPORE 079909

#16-00 SPRINGLEAF TOWER

QTY

**UOM** Code

U/P SGD **AMT** SGD

Remarks: DOA: 27/09/2024 @ 12:55HRS

CLAIMANT: DINGREN ADVISORY PTE LTD / CHOW YUE LIANG (ZHOU YUE LIANG)

TP VEHICLE: GBK5804H

Singapore Dollars: Fifteen Thousand Five Hundred Seven And Cent Twenty-Six Only

SUB TOTAL SGD

14,226.85

GST 9.00% SGD

TOTAL SGD

1,280.41 15,507.26

**OUTSTANDING** 

SGD

15,507.26

Tax SR 14,226.85 **Amount** 

Tax Legend:

Optima Werkz guarantees new parts and labour for one (1) year or up to 30,000km, whichever occurs first. For recon parts, the warranty period is six (6) months or up to 10,000km, whichever comes first.

SR - Standard Rated ZR - Zero Rated OS - Out of Scope

- Warranty claims must be submitted within the warranty period, starting from the date of invoice issued and are subject to verification and inspection by Optima Werkz.
- Warranty claims are only valid when there are no outstanding dues.
- Payment must be made upon completion of repairs and services. A monthly late interest fee of 2% will be applied to any outstanding balance.
- All goods and services sold are considered final and non-refundable
- Deposits paid for the order of parts are non-refundable



Opt for a more convenient and quicker way to pay via Bank Transfer or PayNow:

Beneficiary Name: Optima Werkz Pte Ltd Beneficiary Bank Name: DBS Bank Ltd Bank Account No.:0039441282

Swift Code: DBSSSGSG OR

PayNow UEN: 201212455WDB1

Note: Please include your invoice number under the reference section

# SCHEDULE 2

# PARTICULARS OF VEHICLE AND RENTAL

	Details	of	Veh	icle
7	Total Control of the	Total Control of the last	***************************************	THE PERSON NAMED IN COLUMN

Registration Number Vehicle Model

: SNP 1934Z : ALPHARD HYBRID STANDARD (Auto)

#### Rent

Rent payable is as computed below Base Rent

per day per day per day per day per day

**Total Rent** 

# Security Deposit

The Hirer shall pay to the Company a Deposit of \$\$3,000.00 upon the execution of the Agreement.

Insurance Excess \$2,800 | \$1,500

[To be supplmented after the insurance policy has been obtained]

#### Authorised Driver / Named Driver 5.

Contact No.

The particulars of the Authorised Driver and Named Driver are as listed below:

Name

Name . Address

· Address NRIC / Passport No.

NRIC / Passport No. th the table of the same and the same and the same Driving Licence No. Driving Licence No.

Date of Birth 

Date of Birth Nationality

Nationality Contact No.



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time: 27 Sep 2024 / 16:20:26

Receipt Date/Time: 27 Sep 2024 / 16:20:20

#### Tax Invoice/Receipt

Receipt No.: ITNET-00000-240927-003567

Previous Receipt No.:

	I Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
As a	ult of Insurance Enquiry - GBK5804H t 27 Sep 2024/12:55:00 rance Co: CHINA TAIPING INSURAN				
1	Insurance Enquiry - GBK5804H				
	Enquiry Fee		25.00	2.25	27.25
	20240927161853699359				
		Sub-Total	25.00	2.25	27.25
		Total Before Rounding	25.00	2.25	27.25
		Rounding Difference			0.00
		Total Amount Payable			27.25
		Paid By			
		DICNV20240927161855114330	SGQR	(PayNow)	27.25
		Total			27.25
		Cash Change			0.00
		Tendered Amount			27.25
		Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## TO WHOM IT MAY CONCERN

Signature of Vehicle Registered Owner Company's stamp (if applicable)

## AUTHORIZATION TO ACT

I/We(owner) Dingren Advisory Pte Ud ('the third-party claimant') of
(Address) 618 Sergn 300n Rogal #02-015 (218220) registered owner of
(Vehicle Number) SNP1943 2hereby authorize ('the vehicle repairer workshop')
OPTIMA WERKZ PTE LTD to act for me/us with respect of my/our claim for repair costs and /or
rental and/or loss of use for my/our vehicle number SNP19432 that was damaged pursuant to the accident which occurred on 27109/224 along P957 RPS
damaged pursuant to the accident which occurred on 27/09/2024 along 1957 PSS
Central, L'inggfore involving vehicle number GRK580414
I/We further authorize the workshop to settle my/our above-mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive full payment in the settlement of my/our
claim with full cheque(s) payment being made in the favor of the workshop.
Dated this 28 day of 9 year 2024.
REN ADVISOR