

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SINGAPORE 417883

VEHICLE No: SMR 6513Z

Not Authorised

21/6/24

1/5 \$4800

6 days Teleph. Harry.

1PC	BONNET	R	\$1,410.00 X
1PC	BONNET INSULATOR	11	\$234.00 X
1PC	BONNET INNER RUBBER	11	\$66.80 X
2PCS	BONNET HINGES @\$85.00	11	\$170.00 X
1PC	BONNET LOCK	11	\$190.00 X
1PC	BONNET LOCK FRT BRACKET	11	\$145.80 X
1PC	FRONT BUMPER	680.50 Torn	\$820.00 —
1PC	FRONT BUMPER LOWER CENTRE GRILLE	Torn	\$105.00 —
2PCS	FRONT BUMPER SIDE RETAINERS @\$145.00	680.00 r/scre	\$290.00 12 C
1PC	FRONT BUMPER UNDER COVER	11	\$390.00 X
1PC	FRONT BUMPER FOG LAMP GARNISH N/S	108.20 Torn	\$360.00 —
1PC	FRONT BUMPER REINFORCEMENT	298.30 Bent	\$920.00 —
1PC	FRONT BUMPER TOW COVER	11	\$30.00 X
1SET	FRONT BUMPER CLIPS	39.00 111	\$50.00 —
1PC	FRONT GRILLE	385.40 CNE	\$860.00 —
1PC	FRONT GRILLE OUTER GARNISH	225.30 SCR	\$445.00 —
1PC	FRONT GRILLE 'H' LOGO	11	\$35.00 X
1PC	HEADLAMP N/S	1670.20 CNE	\$4,240.00 —
1PC	HEADLAMP LOWER BRACKET N/S	99.20 CNE	\$360.00 —
1PC	FRONT SUPPORT PANEL	472.80 Bent	\$615.00 —
1PC	FRONT AIR DUCT GARNISH	11	\$255.00 X
1PC	AIR CON CONDENSER	11	\$1,400.00 X
1PC	AIR CON CONDENSER FAN ASSY	11	\$455.00 X
1PC	AIR CON CONDENSER SIDE GARNISH N/S	585.00	\$332.00 X
1PC	RADIATOR	11	\$1,880.00 X
1PC	RADIATOR FAN ASSY	11	\$480.00 X
1PC	FRONT FENDER N/S	R	\$1,300.00 X
1PC	FRONT FENDER INNERSHIELD N/S	168.50 Torn / Torn	\$296.60 —
1PC	FRONT FENDER INNER FRONT ARCH PANEL N/S	299.60 11	\$560.00 —
1PC	FRONT FENDER INNER FRONT SIDE PANEL N/S	285.40 Bent	\$299.00 —
			\$18,994.20

(202

TO CHECK WIRING
TO RESET & REPROGRAMME DIAGNOSIS SYSTEM

\$50.00 20
11 \$100.00 X

TO REFILL AIR CON GAS
 TO MOUNT VEHICLE ON CAR O-LINER
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

	\$120.00	100
	\$380.00	X
	\$1,200.00	880
	\$1,800.00	1100
TOTAL	\$22,644.20	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1-4902.4
 202
 397.52
 2100
 6071.92
 22
 4817