

ASSIGNMENT

Front: _____ Date: _____

Estimate: _____

OD / TP / TP RES / OD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at VO _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Vek: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repair: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNE419J

Yr Regn: 2012 Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q2

c.d. 1498

Colour: Black.

A/C: Insured / Std / NI / NA

Sp. Reading: 49665

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZGA1MA035451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R17.

R: 215/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

D.O.I. 02/10/24.

*Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD A16

COE Expiry

Estimate given during : Yes C
1st Survey : No C

MV : 120K.

PV : 802K.

Nett : 39.8K

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + R.S. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

☐ : _____

Report Format: _____

Report Format: _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0731/2024/KS
DATE : 1-Oct-24
WIP : 32768

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 2/10/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : JALALUDDIN TRAVEL & SERVICES PTE LTD
ADDRESS : BLK 896A TAMPINES STREET 81
#12-854
SINGAPORE 521896
TELEPHONE : HP +65 91006964
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 722007847-02
VEHICLE NO : **SNE 419 J**
MODEL CODE : AUDI Q2 1.5 TFSI S TRONIC
MODEL YEAR : 27/1/2022
ENGINE NO : DPC D33433
CHASSIS NO : WAUZZZGA1MA035451
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 28-Sep-24
PLACE OF ACCIDENT : EAST COAST PARK, SLIP ROAD MERGING INTO ECP

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SNE 419 J

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT AND REAR LID WIPER ASSY.	S/N \$	480.00	✗
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00 1000	
4	TO RESPRAY REAR BUMPER AND REAR LID.	\$	2,300.00 1100	
5	TO RENEW REAR WINDSCREEN AND CARRY OUT WATER SEEPAGE TEST.	S/N \$	680.00	✗
6	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	S/N \$	400.00	✗
7	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		: \$	<u><u>6,912.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 419 J.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER UPPER {Dehd	1	\$ 1,542.00	✓
2	REAR BUMPER LOWER	1	\$ 1,049.00	✓
3	REAR BUMPER TRIM - RH Dehd	1	\$ 100.00	✓
4	REAR BUMPER TRIM - RH neu	1	\$ 68.00	+
5	REAR PARKING AID SUPPORT - RH {neu	1	\$ 28.00	+
6	REAR LIGHT REFLECTOR - RH	1	\$ 36.00	+
7	REAR PARKING AID SENSOR - OUTER {neu	1	\$ 286.00	+
8	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	+
9	REAR REINFORCEMENT BEAM {neu	1	\$ 707.00	+
10	REAR BUMPER HOLDING STRAP	1	\$ 17.00	+
11	REAR LID Repair	1	\$ 2,835.00	+
12	REAR LID ATTACHMENT PARTS neu	1	\$ 3,135.00	+
13	REAR LID PACKING ADHESIVE neu	1	\$ 23.00	+
14	REAR LID BUNGS neu	4	\$ 136.00	+
15	REAR LID LOCK COVER neu	1	\$ 15.00	+
16	REAR LID LOCK neu	1	\$ 323.00	+
17	AUDI EMBLEM {neu	1	\$ 162.00	✓
18	"Q2" EMBLEM	1	\$ 116.00	✓
19	REAR LID SPOILER FOAM STRIPS {neu	1	\$ 162.00	+
20	REAR LID SPOILER FIXING PARTS neu	1	\$ 162.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,913.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNE 419 J.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	1K WINDOW ADHSEIVE	1	\$ 42.00	+
22	PLASTIC PRIMER	1	\$ 100.00	+
23	REAR WINDSCREEN	1	\$ 978.00	+
24	PRIMER	1	\$ 27.00	+
25	TAILLIGHT - RH	1	\$ 1,656.00	+
26	REAR WHEEL ARCH COVER - LH / RH	2	\$ 404.00	✓
27	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 14,620.00	
TOTAL LABOUR CHARGES		:	\$ 6,912.00	
GRAND TOTAL		:	\$ 21,532.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
SURVEYED DATE : *02/10/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT