

QUOTATION

CODE: CUSTOMER: C0006

CHINA TAIPING (SINGAPORE) PTE LT

ADDRESS:

3 ANSON ROAD

SINGAPORE 079909

#16-00 SPRINGLEAF TOWER

MX5 RHT 6EAT NAPPA LEATHER

CONTACT NO.: 6389 6111

CHASSIS NO.: JM6ND2E7AJ0200078 ENGINE NO.:

PE31209667

REG NO.: REGN DATE:

MODEL:

SMU878U 20/04/2018

DOCUMENT NO .:

DOCUMENT DATE:

1627

03/12/2024

POS ID:MU

PAGE NO.:

PRINTED BY:

SERVICE ADV: CSP/OP CODE:

Wong Chun Wei

Wong Chun Wei

DEPT:

WIP NO .:

20710

REF. NO.: DATE IN:

EXT. WTY:

19/04/2023

MILEAGE:

DESCRIPTION:

Item	Description	Stk/Status Qty. Unit Price	Gross amount	
		SGD	SGD	
notes	CHINA TAIPING TP CLAIM		0.00	0
SUB	MZ MX5 UBI		792.00	S
	to remove & replace frt bumper & frt			
	FRT SUPPORT PANEL.			
	AND ALL ACCIDENT AFFECTED AREA.			
	- PO24215			
SUB	MZ MX5 UBI		756.00	S
	to respray frt bumper.		, 30.00	J
	- PO24215			
SUB	MZ MX5 UBI		140.00	S
	TO SUPPLY FRT NUMBER PLATE.		140.00	J
	- PO24215			
SUB	MZ MX5 UBI		1,188.00	S
	TO REMOVE & REPLACE REAR BUMPER.		1,100.00	3
	AND ALL ACCIDENT AFFECTED AREA.			
	- PO24215	•		
SUB	MZ MX5 UBI		1 [12 00	C
	TO RESPRAY REAR BUMPER & REAR FENDER RH.		1,512.00	S
	- PO24215			



TRANSELROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres:

^{*}This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



QUOTATION

CODE: CUSTOMER: C0006

CONTACT NO.: 6389 6111

CHINA TAIPING (SINGAPORE) PTE LT

ADDRESS:

MODEL:

REG NO.:

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

MX5 RHT 6EAT NAPPA LEATHER

SINGAPORE 079909

JM6ND2E7AJ0200078

PE31209667

20/04/2018

SMU878U

DOCUMENT DATE:

PAGE NO .:

2

1627 03/12/2024

POS ID:

DOCUMENT NO .:

MU

PRINTED BY:

SERVICE ADV:

CSP/OP CODE:

Wong Chun Wei

Wong Chun Wei

DEPT:

WIP NO .:

20710

REF. NO.:

DATE IN:

EXT. WTY:

19/04/2023

MILEAGE:

DESCRIPTION:

REGN DATE:

CHASSIS NO.:

ENGINE NO.:

Item	Description		Qty.	Qty. Unit Price			Gross GST amount Code	
				SGD		SGD		
SUB	MZ MX5 UBI TO SUPPLY REAR NUM - PO24215	IBER PLATE.				140.00	S	
SUB	MZ MX5 UBI TO CHECK ELECTRICA FOR PROPER FUNCTIC - PO24215					150.00	S	
SUB	MZ MX5 UBI TO REPROGRAMME A ACCIDENT REPAIR WC - PO24215					180.00	S	
SUB	MZ MX5 UBI SUNDRIES. - PO24215					20.00	S	
N2Y1-50-03XA	BIFRT BUMPER ND		1.00	1,411.96	*ISSUED	1,411.96	S	
EA01-50-037	RIVET	•	4.00	7.34	*ISSUED	29.36	S	
N243-50-0Z1	GROMMET,SCREW	•	2.00	4.64	*ISSUED *ISSUED	9.28	S	
N243-50-0Z5	GROMMET,SCREW		2.00	4.64	*ISSUED	9.28	S	
N243-51-741	MASCOT, FRONT ND		1.00	80.67	*ISSUED	80.67	S	
GD7A-50-EA1	FASTENER	•	4.00	2.62	133010	10.48	S	



TRANS**ELROKARS** Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

^{*}This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



QUOTATION

CODE:

C0006

CONTACT NO.: 6389 6111

CUSTOMER:

CHINA TAIPING (SINGAPORE) PTE LT

MX5 RHT 6EAT NAPPA LEATHER

ADDRESS:

MODEL:

REG NO.:

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

JM6ND2E7AJ0200078

PE31209667

20/04/2018

SMU878U

SINGAPORE 079909

DOCUMENT DATE: POS ID:

DOCUMENT NO.:

1627 03/12/2024

MU

3

PRINTED BY:

PAGE NO .:

SERVICE ADV:

CSP/OP CODE:

Wong Chun Wei

20710

DEPT:

WIP NO .:

REF. NO .:

DATE IN:

EXT. WTY:

19/04/2023

Wong Chun Wei

MILEAGE:

DESCRIPTION:

REGN DATE:

CHASSIS NO .:

ENGINE NO.:

Item	Description	Qty.	Stk/Status Qty. Unit Price			Gross GST amount Code	
			SGD	*ISSUED	SGD		
NAY5-50-2	22XCBREAR BUMPER ND	1.00	1,223.07	*ISSUED	1,223.07	S	
	46A FASTENER	4.00	2.36		9.44	S	
	DZ1A GROMMET,SCREW	2.00	2.36	*ISSUED	4.72	S	
BN8F-50-3		4.00	4.64	*ISSUED	18.56		
N243-50-E	K1ABICOVER,TOWING HOOK ND	1.00	2.36	*NO STOCK	2.36	-	
N243-50-1	TOB MESH, FRONT BUMPER ND	1.00	309.75	*NO STOCK	309.75	S	
N243-50-7	· · · · · · · · · · · · · · · · · · ·	1.00	130.73	*ISSUED	130.73	S	
BN8F-50-3		2.00	4.64	*ISSUED	9.28	S	
B33J-51-83	,	8.00	6.49	*NO STOCK	51.92	S	
N243-50-3	(, , , , - , - , , - , , - , , - , , -	1.00	89.09	*ISSUED	89.09	S	
EA01-50-03	37 RIVET	1.00	7.34	100000	7.34	S	

	*	GST Code	Rate	Service/Goods	GST
Parts	3,407.29	0	-		_
Surcharge	0.00	S	9.00%	8,285.29	745.68
Labour	4,878.00				
Menus	0.00				
*This is only an e	estimate from ou	r visual inspectio	n and sho	uld there he more dama	ges found during

the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross * —	8,285.29	745.68	9,030.97
Less: Deposit**	0.00	0.00	0.00
Amount Due	8,285.29	745.68	9,030.97

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE No.

Customer signature

Authorised signature

TRANSELROKARS Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres: 200m-200m

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417