(08/11	/13) <	wef
ACC	REC	BY: MCreus

REF: CS/C7/24/00036/4

ASSIGNMENT
------------

From: Date:	Veh No: SMU 8784 Yr Regn: 20/04/18
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or Hard 737 2-3
To Inspect Vehicle No: SMU 8784	Make: Mezdo Mx-5 c.c /778
at Workshop m/s Trons Euro 985	Colour Gray A/C: Insured / Std / NI / NA
of	Sp.Reading 39078 T/Radio: Insured / Std / NI / NA
Insured: SNP344VM	Eng/No:
Policy No.	C/No: JM6ND2E7AJ0200078
Claims No.	Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
(P)	Tyre Size: F: 215/45717
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal6mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 9 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 28/09/24 D.O.I. 04/10/24
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS 667 A	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	Rear ols , And
Date: Person Contacted: LTAS 44515	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction 200 224	
	. ,
- Ch	
Date/Time, File Pass to? : Preli. Report	ays Of Repair:
1) : Final Report R	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee:	: Site Insp (\$)s+Rs,si
	: Interview (\$) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$	:Weekend (\$)
	TOTAL



Not Arthoral
mens
4/10/24
5-6 dys aluphe selve panty

CODE:

C0006

CUSTOMER:

CONTACT NO.: 6389 6111

ADDRESS:

MODEL:

**REG NO.:** 

CHINA TAIPING (SINGAPORE) PTE LT

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

MX5 RHT 6EAT NAPPA LEATHER

SINGAPORE 079909

JM6ND2E7AJ0200078

PE31209667

20/04/2018

**SMU878U** 

PAGE NO .:

**DOCUMENT NO.:** 

1500

01/10/2024

**DOCUMENT DATE:** POS ID:MU

PRINTED BY:

Lee Yao Sheng

SERVICE ADV:

CSP/OP CODE:

Lee Yao Sheng

DEPT:

WIP NO .:

20710

REF. NO .:

DATE IN:

EXT. WTY:

19/04/2023

MILEAGE:

0

CHASSIS NO.:

**ENGINE NO.:** 

**REGN DATE:** 

DESCRIPTION:	and there will be a second		4	-	Stk/Status	Gross	GST
Item	Description		Qty.	<b>Unit Price</b>		amount	
				SGD	4.44	SGD	-
NOTES	CHINA TAIPING TP CLAIM				_	0.00	O
SUB		792			792	2,376.00	3
	FRT SUPPORT PANEL.	,,,					
	AND ALL ACCIDENT AFFECTED AREA.				7.1	1,512.00	S
SUB	TO RESPRAY FRT BUMPER.				756	140.00	S
SUB	TO SUPPLY FRT NUMBER PLATE.				sin	1,584.00	S
SUB	TO REMOVE & REPLACE REAR BUMPER.				1188	1,304.00	9
	AND ALL ACCIDENT AFFECTED AREA.				. 1113	2,268.00	S
SUB	TO RESPRAY REAR BUMPER & REAR FENDER R	H. 756			15/2 su	140.00	5
SUB	TO SUPPLY REAR NUMBER PLATE.					250.00	s X
SUB	TO CARRY OUT BODY CAVITY				11	230.00	9
	PRESERVATION.				150	250.00	S
SUB	TO CHECK ELECTRICAL SYSTEM				130	200.00	8
	FOR PROPER FUNCTIONING.				180	300.00	S
SUB	TO REPROGRAMME AFTER THE				/80		
	ACCIDENT REPAIR WORKS.			AM	*NO STOCK	50.00	S
SUB	SUNDRIES.	DIL	1.00	1.411.96	*NO STOCK	1,411.96	5
	BIFRT BUMPER ND	nu	4.00		*NO STOCK	29.36	5
EA01-50-037	RIVET GROMMET,SCREW	rei	2.00	4.64	NO STOCK	9.28	S
N243-50-0Z1	OKOMMET, SCREAM	1000				to accelle	

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

"Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

LKK Auto Consultants hence notify

• To resurvey before/after spray painting

To display damaged part(c) six the recurvey

Parts prices are subject to confirmation

o Third party survey is on a "Without Projudice" basis

No illagal modification(s) is allowed

• Supplementary item(s) must be resurveyed mind is subject to final approval from Insurance Company

Acknowledged by Repairer

TRANSEURARS Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.19913859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres:

Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417

23 Leng Kee Road Singapore 159095 5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Tel: 6603 6118 Service Tel: 6603 6128



CODE:

C0006

CUSTOMER:

CHINA TAIPING (SINGAPORE) PTE LT

ADDRESS:

3 ANSON ROAD

**#16-00 SPRINGLEAF TOWER** 

SINGAPORE 079909

PAGE NO .: DOCUMENT NO .:

1500

2

**DOCUMENT DATE:** POS ID:

01/10/2024 MU

PRINTED BY:

Lee Yao Sheng Lee Yao Sheng

SERVICE ADV: CSP/OP CODE:

DEPT: WIP NO .: 20710

CONTACT NO.: 6389 6111

MODEL:

MX5 RHT 6EAT NAPPA LEATHER

**CHASSIS NO.:** 

JM6ND2E7AJ0200078

ENGINE NO .: **REG NO.:** 

PE31209667 **SMU878U** 

REF. NO .: DATE IN: EXT. WTY:

19/04/2023

**REGN DATE:** 

20/04/2018

MILEAGE:

0

DESCRIPTION:			Stk/Status	Gross	GST
Item	Description	Q	ty. Unit Price	amount	Code
item	Description.		SGD ·NO STOCK	SGD	
N243-50-0Z5 N243-50-0Z5 N243-50-051 N314-50-0T1A N314-50-0U1/ N243-50-A11 N243-50-1T0B N243-50-7Z2E GD7A-50-EA1 N243-50-070E NA1J-50-A21 FD01-68-AC3 BN8F-50-355 N243-51-9H1 N243-51-9H1 BN8F-50-355 B33J-51-833	A RETAINER LH, FRT BUMPER ND BBCOVER, TOWING HOOK-BU ND MASCOT, FRONT ND MESH, FRONT BUMPER ND D BRACKET(R), GRILLE ND FASTENER D REINF., FRONT BUMPER ND GUIDE, AIR ND FASTENER RIVET SKIRT(R), FRONT AIR ND SKIRT(L), FRONT AIR ND RIVET RIVET, SPLASH SHIELD	1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1 1.1	SGD •NO STOCK  00 4.64 •NO STOCK  00 25.96 •NO STOCK  00 25.96 •NO STOCK  00 13.91 •NO STOCK  00 36.16 STOCK  00 36.16 STOCK  00 309.75 •NO STOCK  00 1,143.51 •NO STOCK  00 1,143.51 •NO STOCK  00 29.42 •NO STOCK  00 29.42 •NO STOCK  00 29.42 •NO STOCK  00 203.22 •NO STOCK  00 203.22 •NO STOCK  00 203.22 •NO STOCK  00 4.64 •NO STOCK  00 203.22 •NO STOCK  00 4.64 STOCK  00 6.49 •NO STOCK  00 5,458.77 •NO STOCK	9.28 25.96 25.96 13.91 12.98 36.16 80.67 309.75 130.73 10.48 1,143.51 29.42 5.31 18.56 203.22 203.22 9.28 51.92 5,458.77	こうつつつつつこうしつつつつながない
N316-51-0K0E N316-51-0L0E			00 5,458.77	5,458.77	SX



TRANSEUROKARS
Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres: 5 Ubi Close Singapore 408605 Sales Tel: 6395 8888 Service Tel: 6395 8899

23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 68461700 Service Fax: 6744 9402 Sales Fax: 6476 7073 Service Fax: 6476 7417

<sup>\*</sup>This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

<sup>\*</sup>Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



CODE:

CHASSIS NO.: JM6ND2E7AJ0200078

PE31209667

20/04/2018

**SMU878U** 

C0006

CHINA TAIPING (SINGAPORE) PTE LT

CUSTOMER: ADDRESS:

MODEL:

**REG NO.:** 

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

MX5 RHT 6EAT NAPPA LEATHER

SINGAPORE 079909

PAGE NO.: DOCUMENT NO .:

1500

**DOCUMENT DATE:** 

01/10/2024

POS ID:

PRINTED BY:

MU Lee Yao Sheng

SERVICE ADV:

CSP/OP CODE:

Lee Yao Sheng

DEPT:

WIP NO .:

20710

REF. NO .:

DATE IN:

EXT. WTY:

19/04/2023

MILEAGE:

**ENGINE NO.:** 

**REGN DATE:** 

CONTACT NO.: 6389 6111

Item	Description		Qty.	Unit Price	Gross amount ( SGD	
N243-53-16XA NAY5-50-22XC B45A-56-146A	BREAR BUMPER ND FASTENER GROMMET,SCREW RIVET BRACKET'A' ND BRACKET'B' ND RETAINER(R),REAR BUM ND RETAINER(L),REAR BUM ND BUMPER(R),REAR ND BUMPER(L),REAR SHIELD(R),SPLASH-R.B ND SHIELD(L),SPLASH-R.B ND RIVET BRACKET(L),REAR BUMP ND BRACKET(L),REAR BUMP ND	27 27 27 20 20 20 20 20 20 20 20 20 20 20 20 20	2.00 1.00 1.00 4.00 2.00 4.00 1.00 1.00 1.00 1.00 1.00 2.00 1.00 1	2.95 *NO STOCK 522.07 *NO STOCK 160.99 *NO STOCK 1,223.07 STOCK 2.36 *NO STOCK 2.36 *NO STOCK 2.36 *NO STOCK 2.36 *NO STOCK 11.13 *NO STOCK 11.13 *NO STOCK 11.13 *NO STOCK 25.96 *NO STOCK 25.96 *NO STOCK 89.09 *NO STOCK 89.09 *NO STOCK 7.34 *NO STOCK 30.85 *NO STOCK 30.85 *NO STOCK 34.06 *NO STOCK	5.90 522.07 160.99 1,223.07 9.44 4.72 18.56 2.36 2.36 11.13 11.13 25.96 25.96 89.09 89.09 14.68 30.85 30.85 34.06 34.06	S S S S S S S S S S S S S S S S S S S



TRANSELROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres: 5 Ubi Close Singapore 408605 Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 6476 7073 Service Fax: 6476 7417

<sup>\*</sup>This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

<sup>\*</sup>Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



CODE:

C0006

CUSTOMER:

CHINA TAIPING (SINGAPORE) PTE LT

ADDRESS:

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

PAGE NO .:

**DOCUMENT NO.:** 

1500

**DOCUMENT DATE:** 

01/10/2024 MU

POS ID:

PRINTED BY:

Lee Yao Sheng

SERVICE ADV:

CSP/OP CODE:

DEPT:

Lee Yao Sheng 20710

CONTACT NO.: 6389 6111

MODEL:

MX5 RHT 6EAT NAPPA LEATHER

**CHASSIS NO.:** ENGINE NO .:

JM6ND2E7AJ0200078 PE31209667

**REG NO.: REGN DATE:**  **SMU878U** 20/04/2018 WIP NO .: REF. NO .: DATE IN:

19/04/2023

EXT. WTY: MILEAGE:

**DESCRIPTION:** 

DESCRIPTION	Selfi fiert			Stk/Status			
Item	Description	Q	Qty. Unit Price			amount Code	
				SGD CTOCK	SGD		
DFR5-50-251 NA1J-50-260 NA1P-51-721 N243-50-2G2 N243-51-771 NC10-50-2G2	O CORD, SHORT ND 1 2:SENSOR, ULTRASONIC DJ/DK BRACKET, BUMPER SKYACTIV REINF., REAR BUMPER ND ORNAMENT, CAR NAME-RE ND 2 SEAL, RUBBER ND ORNAMENT ND 2 SEAL, RUBBER ND 2 SEAL, RUBBER ND	1, 4, 1, 1, 2, 1, 4,	.00 1 .00 7 .00 7	3.29 *NO STOCK 95.89 *NO STOCK 59.14 *NO STOCK 4.64 *NO STOCK 63.21 *NO STOCK 59.76 *NO STOCK 9.28 *NO STOCK 71.65 *NO STOCK 1.86 *NO STOCK 2.95 *NO STOCK	6.58	55555555555555555555555555555555555555	
N244-51-240 NC10-50-2G2 C274-50-133 GI6A-51-14Y	G LAMP(R),RR COMB ND  B FASTENER  IA GROMMET,SCREW  D LAMP(R),BACK UP ND  2 SEAL,RUBBER ND  NUT,CLIP	1. 2. 2. 1. 2. 2. 2.	.00 8 .00 .00 .00 .00 1 .00 .00	99.59 STOCK 3.71 *NO STOCK 2.36 *NO STOCK 98.92 *NO STOCK 1.86 *NO STOCK 2.36 *NO STOCK 14.84 *NO STOCK 2.36	899.59 7.42 4.72 198.92 3.72 4.72 29.68 2.36	S7 S7 S7 S7 S7 S7 S7	

	•	GST Code	Rate	Service/Goods	GST
Parts	20,156.11	0			-
Surcharge	0.00	_	9.00%	29,026.11	2,612.35
Labour	8,870.00				Wennershift & J
Menus	0.00			util these he more dam	car found during
*This is only an	estimate from ou	visual inspection	n and sho	uld there be more dame provat before proceeding	g with the repairs.

	Before GST	GST	Total
Gross	29,026.11	2,612.35	31,638.46
Less: Deposit**	0.00	0.00	0.00
Amount Due	29,026.11	2,612.35	31,638.46

<sup>\*</sup>Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

"Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE No.

Date:

Customer signature

Authorised signature

TRANSEURAS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

zoom-zoom

 Showrooms & Service Centres:
 23 Leng Kee Road Singapore 159095

 5 Ubi Close Singapore 408605
 23 Leng Kee Road Singapore 159095

 6 Sales Tel: 6395 8888 Service Tel: 6395 8899
 Sales Tel: 6603 6118 Service Tel: 6603 6128

 6 Sales Fax: 68461700 Service Fax: 6744 9402
 Sales Fax: 6476 7073 Service Fax: 6476 7417

Page 3 of 3

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	CI NIDIC
Owner ID Type:	Singapore NRIC
Owner ID:	667A
Vehicle Details	CMI 10701 I
Vehicle No.:	SMU878U
Vehicle to be Exported:	No /
Intended Deregistration Date:	03 Oct 2024
Vehicle Make:	MAZDA
Vehicle Model:	MX-5 HARDTOP 2.0 AT 2WD
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	PE31209667
Chassis No.:	JM6ND2E7AJ0200078
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$38,149.00
Original Registration Date:	20 Apr 2018
First Registration Date:	20 Apr 2018
Transfer Count:	2
Actual ARF Paid: Intended PARF Rebate Details	\$45,409.00 ZZ 704
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Apr 2028
PARF Rebate Amount: Intended COE Rebate Details	\$29,515.00
COE Expiry Date:	19 Apr 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,322.00
COE Rebate Amount:	\$15,000.00
Total Rebate Amount: Message	\$44,515.00

The information contained herein is correct as at 03 Oct 2024

### sgcarmart

בֹל			
:=	$\otimes$	Login	Sign U

New	Used	Electric	Loan	Rent	Sell	Directory	e-Shop	Insurance	Articles	Forum	Res
Ξ									Ć	μ	8
	sed Cars Listi Category	ing Q	Filter		Se	earch		Œ	)Save Searc	h	
2018											
	icles Car	Make	Car M	odel		Price Range	Depreciat	ion (201	8	Mileage	è
DIRECT O For old		nents, view E	xpired ads	2.0M The I famil clear cars you i	legendar ly of kee ned, with available	/mth ry MX-5 Miata n enthusiast n low mileage e on the mark interested in	83 Owners  Tip top imr car owners. I  One of the ket today at a	naculate cond Routinely servi only few man I very reasonal	ition, mainta ced, regular ual transmis	ained by a ly washed sion sport is is the ca	d and
					(	☐Save Searc	:h				
1 Veh	icles Car	Make	Car M	odel	F	Price Range	Depreciat	ion 201	8	Mileage	
					< Pre	ev 1 [	Next >		20	results	/page
Conta	ct Us										
Career											
f O	Sgcarma  Inload on the p Store		EXPLORE IT O	N lery							
								, hybrid car, C			
								om new car d solar film, car			
								over, and moto			

Uiew page in Desktop

Terms of Service | Privacy | PDPA ©2004-2024 Sgcarmart, Singapore. All rights reserved.


car blog and coe prices. Find Rental Cars for short term rental, long term lease, private hire cars, wedding cars and cars

for p-plate probation drivers.

### sgcarmart

Login | Sign Up

New Used Electric Loan Rent Sell Directory e-Shop Insurance Articles Forum Res



Contact Us Careers

Follow Sgcarmart.com

Download on the Google Play CAMORE IT ON AppGallery

Sgcarmart is the number one car classifieds for buying vehicles like sports car, hybrid car, COE cars, OPC Car, hatchback, stationwagon, MPV, SUV, van, truck & parallel imported cars. Buy from new car dealer, parallel importer, car auction, etc. Also find useful products & services like car audio, car polishing, solar film, car accessories, car parts, car repair, car workshop, car bodykit, car tyre, sport rims, car mat, car stickers, mover, and motor insurance. Check out our car blog and coe prices. Find Rental Cars for short term rental, long term lease, private hire cars, wedding cars and cars for p-plate probation drivers.

\_\_\_ View page in Desktop

Terms of Service | Privacy | PDPA ©2004-2024 Sgcarmart, Singapore. All rights reserved.