

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV No. : SAC2401103

INV Date : 23-10-2024

Reference CS3/III24100048/Rqp3m4

Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SLV 1516P
Insured Veh. GBM 2315L
Claim No. MFL2024D0011819
Policy No. D19MFL0005549_04
Accident Date 17/09/2024
Inspection Date 02/10/2024

Description	Amount
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	170.00
- First Inspection 02.10.2024 12.28pm	0.00
- Dismantle Inspection 03.10.2024 03.42pm	0.00
- After Repair Inspection 09.10.2024 03.44pm	0.00
Merimen Fee	12.00
Sub-Total	182.00
GST (9%)	16.38
Grand Total	198.38

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML
