



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA2 IPM HB HIGH WHITE
CHASSIS NO.: JM6DJ2HAA01200187
ENGINE NO.: P520484407
REG NO.: ET9822X
REGN DATE: 30/11/2017

PAGE NO.: 1
DOCUMENT NO.: 1593
DOCUMENT DATE: 16/11/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV:
CSP/OP CODE: Wong Chun Wei
DEPT: I
WIP NO.: 20732
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	MS FIRST CAPITAL TP CLAIM				0.00	O
SUB	MZ 2 UBI				1,584.00	S
	TO REMOVE & REPLACE REAR BUMPER, END					
	PANEL & REAR FENDER LOWER PANEL LH.					
	AND ALL ACCIDENT AFFECTED AREA.					
	- PO23537					
SUB	MZ 3 UBI				1,512.00	S
	TO RESPRAY REAR BUMPER, END PANEL &					
	REAR FENDER LOWER PANEL LH.					
	- PO23537					
SUB	MZ 3 UBI				180.00	S
	TO TRANSFER REVERSE SENSORS.					
	- PO23537					
SUB	MZ 3 UBI				70.00	S
	TO SUPPLY NUMBER PLATE.					
	- PO23537					
SUB	MZ 3 UBI				120.00	S
	TO CHECK ELECTRICAL SYSTEM					
	FOR PROPER FUNCTIONING.					
	- PO23537					

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



QUOTATION

CODE: F0001
CUSTOMER: MS FIRST CAPITAL INSURANCE LTD
ADDRESS: 16 RAFFLES QUAY
#42-01
HONG LEONG BUILDING
SINGAPORE 048581
ATTN: MOTOR CLAIM DEPT
CONTACT NO.: 6507 3848
MODEL: MAZDA2 IPM HB HIGH WHITE
CHASSIS NO.: JM6DJ2HAA01200187
ENGINE NO.: P520484407
REG NO.: ET9822X
REGN DATE: 30/11/2017

PAGE NO.: 2
DOCUMENT NO.: 1593
DOCUMENT DATE: 16/11/2024
POS ID: MU
PRINTED BY: Wong Chun Wei
SERVICE ADV:
CSP/OP CODE: Wong Chun Wei
DEPT: I
WIP NO.: 20732
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
SUB	MZ 3 UBI TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. - PO23537				150.00	S
SUB	MZ 3 UBI SUNDRIES. - PO23537				20.00	S
DH4T-50-221	BEREAR BUMPER DJ W/SENSOR	1.00	1,024.24	*ISSUED		
B45A-56-146A	FASTENER	7.00	2.36	*ISSUED	1,024.24	S
BHN1-50-0Z1A	GROMMET,SCREW	4.00	2.36	*ISSUED	16.52	S
GS1D-50-EM1A	TAPE,PROTECTOR	5.00	7.42	*ISSUED	9.44	S
KD47-67-UC5A	RETAINER REV SENSOR	4.00	15.77	*ISSUED	37.10	S
GMK6-67-UC1	SENSOR,ULTRASONIC GJ/GL	1.00	184.59	*ISSUED	63.08	S
KD47-67-UC1	6.SENSOR,ULTRASONIC SKYACTIV	1.00	184.59	*ISSUED	184.59	S

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	1,519.56	O	-	-			
Surcharge	0.00	S	9.00%	5,155.56	464.00	5,619.56	
Labour	3,636.00						
Menus	0.00						
Gross					5,155.56	464.00	5,619.56
Less: Deposit**					0.00	0.00	0.00
Amount Due					5,155.56	464.00	5,619.56

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date: _____ Customer signature _____ Authorised signature _____
TRANSEUROKARS Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Eurokars Group Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402
23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417