

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

To: MS FIRST CAPITAL INSURANCE LTD  
16 RAFFLES QUAY  
#42-01 HONG LEONG BUILDING

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JOANNE YONG

Date: 08/10/2024

### PRELIMINARY ADVICE

Vehicle No	ET 9822X	Accident Date	29/09/2024
Make	MAZDA MAZDA 2 5-DOOR	Policy No.	SHA 7198S
	HATCHBACK		
Assignment Date	02/10/2024	Excess	-
Inspection Date	04/10/2024	Est. Duration of Repair	3 days

Inspected At: TRANS EUROKARS PTE LTD

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Workshop Estimate Amount:	\$14,244.79
Revised Estimate Amount:	\$5,155.56
"Check" Items Amount	\$0.00
Total	\$5,155.56

### Total Loss Consideration

Book Value	\$0.00
Market Value	\$40,000.00
COE / PARF Rebate	\$17,891.00
Salvage Value	\$0.00
Margin for Repair	\$22,109.00

### Remarks

- [ ] The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- [ ] The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- [ ] Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.