

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

**Tax Invoice**

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE #03-03  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. : SAC2401004

INV Date : 15-10-2024

Reference CS3/SMO24100051/Knp3m4

Code SMO

**PROFESSIONAL SERVICE FEE**

Vehicle No. GBE 4421S  
Insured Veh. YQ 1030X  
Claim No. CMTD2403161/JYC  
Policy No. D24MTPCVE001356  
Accident Date 28/09/2024  
Inspection Date 07/10/2024

Description	Amount
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 08.10.2024)	20.00
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 10.10.2024)	20.00
Sub-Total	160.00
GST (9%)	14.40
Grand Total	174.40

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

**LKK Auto Consultants Pte Ltd**

**SML**

---