

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 24.06.2024

TO : **INCOME** MOTOR CLAIMS DEPTS (SUPPLEMENTARY)
VEHICLE NO : **SLJ7070G**
MODEL : **TOYOTA LEXUS NX350H**
DATE OF ACCIDENT : 19.06.2024
TIME OF ACCIDENT : 11:05 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE SIDE SENSOR <i>cracked</i>	1	\$ 1,680.00	\$ 1,680.00

TOTAL PRICE \$ 1,680.00
LESS 25% 10% \$ 420.00
SUB TOTAL PRICE \$ 1,260.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ -
TOTAL REPAIR COST : \$ -

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Supplementary: 1089

Adrian Lg
Slg.

1210

1210