



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Acknowledged by Repairer Mr Tan Kim Lee 6 Kitchener Link #10-11 Singapore 207227 Mobile: 97638155	
		Document No.		
		0		
		Document Date		
		01/10/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	19/03/2019	SMJ7447S	0	23314	66TP/SMJ7447S/300924
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B23F3801168820	2NRX421529	60	Shashitharan	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VEH NO:SBS7447S ACC DATE:27/09/24 DRIVE IN:28/09/24 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50.100.00
2	B	BP-LAB2 CHECK WIRING ANF CONDUCT LEAK TEST				198.00
3	B	BP-LAB2 TRANSFER RH FRT AND REAR DOOR MECHANISM				792.00
4	B	BP-LAB2 R/I REAR WINDSCREEN				792.00
5	B	BP-LAB2 R/I INTERIOR UPHOLSTERY				792.00
6	B	BP-LAB2 DRILL HOLE AND INSTALL RVERSE SENSOR				198.00
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
8	B	BP-MECH2 CONDUCT WHEEL ALIGNMNET				198.00
9	B	BP-MECH2 TRANSFER TYRE TYRE TO NEW RIM				198.00
10	Z	BP-SLANT SUPPLY SEALANT (NETT)				300.00
11	B	BP-LAB2 TRANSFER BOOTLID MECANISM AND REVERSE CA MERA				396.00
12	B	BP-LAB2 REPL ACC AFF PARTS AND PANEL				3960
13	B	BP-RES2 RESRPAY ACC AFF AREA				6336.00
14	1	S75895-0D270 TAPE, MOULDING, NO.1	2.00	69.90		5248.00
						139.80

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total Tanfikh 97495749 WP' 02/10/24 @ 330pm tanfikh@lkhauto.com 10 days ✓ p/p Resurvey before parts Less Amount Due
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details					
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Tan Kim Lee 6 Kitchener Link #10-11 Singapore 207227 Mobile: 97638155					
		Document No.						
		0						
		Document Date						
		01/10/2024						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	NSP151R	AEXGKT G1	19/03/2019	SMJ7447S	0	23314	66TP/SMJ7447S/300924	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B23F3801168820		2NRX421529	60	Shashitharan	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	2	S52161-0K040	PIECE, RR BUMPER			4.00	5.80	rec ✓ 23.20 ✓
16	3	S52159-0U963	COVER, RR BUMPER L/C			1.00	818.00	de ✓ 818.00 ✓
17	4	S52591-0D400	SEAL, RR BUMPER SIDE			1.00	101.00	rec ✓ 101.00 ✓
18	5	S52575-0D340	RETAINER, RR BUMPER			1.00	236.70	car ✓ 236.70 ✓
19	6	S81910-0D050	REFLECTOR ASSY, REFL			1.00	129.90	car ✓ 129.90 ✓
20	7	S58307-0D480	PANEL SUB-ASSY, BODY			1.00	1134.50	bt ✓ 1134.50 ✓
21	8	S58315-0D060	EXTENSION, RR FLOOR			1.00	194.10	Rv ✓ 194.10 ✓
22	9	S61063-0D090	TROUGH SUB-ASSY, LUG			1.00	161.30	bt ✓ 161.30 ✓
23	0	S61601-0D260	PANEL SUB-ASSY, QUAR			1.00	1399.40	buc ✓ 1399.40 ✓
24	1	S62940-0D060	DUCT ASSY, QUARTER V			1.00	48.20	na ✓ 48.20 ✓
25	2	S64401-0D360	PANEL SUB-ASSY, LUGG			1.00	1218.30	bt ✓ 1218.30 ✓
26	3	S64461-0D180	WEATHERSTRIP, LUGGAG			1.00	242.90	ur ✓ 242.90 ✓
27	4	S64503-0D090	ARM SUB-ASSY, LUG CO			2.00	91.00	un ✓ 182.00 ✓
28	5	S75921-0D110	TAPE, BLACK OUT, NO.			1.00	66.50	rec ✓ 66.50 ✓
29	6	S68610-0D131	CHECK ASSY, FR DOOR			1.00	255.50	un ✓ 255.50 ✓
30	7	S67001-0D430	PANEL SUB-ASSY, FR D			1.00	1688.50	bt ✓ 1688.50 ✓
31	8	S69210-0D140	HANDLE ASSY, FR DOOR			1.00	612.80	un ✓ 612.80 ✓
32	9	S69217-0K370	COVER, FR DOOR OUTSI			1.00	47.00	aut ✓ 47.00 ✓
33	0	S69217-0K380	COVER, FR DOOR OUTSI			1.00	84.10	aut ✓ 84.10 ✓
34	1	S69030-0D370	LOCK ASSY, FR DOOR W			1.00	840.30	un ✓ 840.30 ✓
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd								
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Tan Kim Lee 6 Kitchener Link #10-11 Singapore 207227 Mobile: 97638155
	Document No. 0	
	Document Date 01/10/2024	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	NSP151R	AEXGKT G1	19/03/2019	SMJ7447S	0	23314	66TP/SMJ7447S/300924

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B23F3801168820	2NRX421529	60	Shashitharan	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
35	2	S68710-0D050 HINGE ASSY, FR DOOR,	1.00	135.40		135.40
36	3	S68730-02100 HINGE ASSY, FR DOOR,	1.00	153.00		153.00
37	4	S67003-0D650 PANEL SUB-ASSY, RR D	1.00	1448.40		1448.40
38	5	S75923-0D270 TAPE, BLACK OUT, NO.	1.00	60.40		60.40
39	6	S67871-0D230 WEATHERSTRIP, RR DOO	1.00	248.40		248.40
40	7	S68630-0D170 CHECK ASSY, RR DOOR,	1.00	255.50		255.50
41	8	S69210-0K200 HANDLE ASSY, DOOR, O	1.00	204.10		204.10
42	9	S69227-0K200 COVER, RR DOOR OUTSI	1.00	84.10		84.10
43	0	S69203-0D210 FRAME SUB-ASSY, RR D	1.00	268.20		268.20
44	1	S69050-0D200 LOCK ASSY, RR DOOR W	1.00	779.30		779.30
45	2	S68750-0D030 HINGE ASSY, RR DOOR,	1.00	135.40		135.40
46	3	S68770-0D030 HINGE ASSY, RR DOOR,	1.00	135.40		135.40
47	4	S69803-0D230 REGULATOR SUB-ASSY,	1.00	262.10		262.10
48	5	S75431-02090 EMBLEM, LUGGAGE COMP	1.00	85.60		85.60
49	6	T90975-02063 EMBLEM, SYMBOL	1.00	66.30		66.30
50	7	S75442-0D400 PLATE, LUGGAGE COMPT	1.00	63.20		63.20
51	8	S75444-0D700 PLATE, LUGGAGE COMPT	1.00	49.20		49.20
52	9	S81550-0DA40 LAMP ASSY, RR COMBIN	1.00	976.00		976.00
53	0	S81580-0D490 LAMP ASSY, RR, RH	1.00	637.00		637.00
54	1	S52562-0D130 RETAINER, RR BUMPER,	1.00	91.40		91.40

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
THIRD PARTY CLAIM				S1000020 / TPCLAIM		Mr Tan Kim Lee 6 Kitchener Link #10-11 Singapore 207227 Mobile: 97638155			
				Document No. 0					
				Document Date 01/10/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2019	NSP151R	AEXGKT G1	19/03/2019	SMJ7447S	0	23314	66TP/SMJ7447S/300924		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
MR2B23F3801168820		2NRX421529	60	Shashitharan	--/--/----		0.00	--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount	
55	2	S42611-0DF50 WHEEL, DISC			1.00	2687.30		2687.30 ✓	
56	3	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		216.00 ✓	
57	4	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00 ✓	
58	5	T08826-08115 PANEL BONDING AD			1.00	267.20		267.20 ✓	
For & on behalf of				Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd								34,878.90	
				Please acknowledge receipt of vehicle				GST 9.00%	
						Parts 19,132.90		3,139.10	
						Labour 15,746.00			
						Sublet 0.00			
						Lubrication/Fluid 0.00		Less 0.00	
						Others 0.00		Amount Due 38,018.00	

Customer Copy