



Liu's Brother Auto Engineering Workshop

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: China Taiping Insurance (Singapore) Pte Ltd
Address Motor Claims Department
3 Anson Road #16-00
Springleaf Tower Singapore 079909

Ref Date:
Ref No:
Vehicle No:
Model / Make:

02/10/2024
GBF272B240917
GBF272B
Fiat Doblo
Maxi 1.6 MTJ AMT Glaze

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Bumper	\$ 745.00	1	\$ 745.00		cur/de ✓
2		Bumper Clips 1 set	\$ 65.00	1	\$ 65.00	SN	ru 305/N
3		Tail Lamp Rh	\$ 462.70	1	\$ 462.70		one ✓
4		Tailgate "Professional" Emblem	\$ 163.50	1	\$ 163.50		su x
5		Tailgate "6 PAX" Sticker	\$ 15.00	1	\$ 15.00	SN	ru 105/N
6		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 1,200.00		300
7		To putty & spray painting & including touch up paint on accident affected			\$ 900.00		400
8		Remove and refix rear reverse sensor			\$ 100.00		30
9		To check all wiring & electrical component for proper function			\$ 120.00		20

Total Parts & Labour of estimate for damaged vehicle

\$ 3,771.20

Total amount in Lumpsum Basis for repaired vehicle



SDL

Liu's Bro Auto Engrg Wks

Not Authorized
Mercur
3/10/24
h/c \$1500/
3 days.
Abu shif. Akkapp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-1207-7
02
P-1088-93
S.W 40
h-750
1876.93
203
1501.