

TSL AUTO PRO SELECTION PTE LTD

BLK 1 KAKI BUKIT AVE 6 #01-06 AUTOBAY @KAKI BUKIT
SINGAPORE 417883

TO	: NTUC	DATE	3/10/2024
VEHICLE NO	: SMA22005 (2018)	Veron.	
VEHICLE MODEL	: MITSUBISHI ECLIPSE CROSS		
CHASSIS NO	: JMAXTGK1WJZ001415		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Torn</i>	1	\$ 605.00	\$ 605.00
2	REAR BUMPER SIDE HOLDER <i>new</i>	1	\$ 28.00	\$ 28.00
3	REAR BUMPER LOWER GARNISH <i>new</i>	1	\$ 285.00	\$ 285.00
4	REAR FENDER <i>Repair</i>	1	\$ 925.00	\$ 925.00
5	REAR FENDER ARC GARNISH <i>new</i>	1	\$ 181.00	\$ 181.00
6	TAILLAMP <i>new</i>	1	\$ 693.00	\$ 693.00
7	REAR DOOR <i>Dented</i>	1	\$ 954.00	\$ 954.00
8	REAR DOOR LOCK <i>new</i>	1	\$ 298.00	\$ 298.00
9	REAR DOOR WEATHERSTRIPE <i>new</i>	1	\$ 259.00	\$ 259.00
10	REAR DOOR LOWER PROTECTOR <i>new</i>	1	\$ 266.00	\$ 266.00
11	REAR DOOR GLASS <i>new</i>	1	\$ 460.00	\$ 460.00
12	REAR DOOR GLASS CHROME MOULDING <i>new</i>	1	\$ 155.00	\$ 155.00
13	FRONT DOOR <i>Dented</i>	1	\$ 989.00	\$ 989.00
14	FRONT DOOR LOCK <i>new</i>	1	\$ 295.00	\$ 295.00
15	FRONT DOOR WEATHERSTRIPE <i>new</i>	1	\$ 268.00	\$ 268.00
16	FRONT DOOR LOWER PROTECTOR <i>new</i>	1	\$ 275.00	\$ 275.00
17	FRONT DOOR GLASS <i>new</i>	1	\$ 495.00	\$ 495.00
18	FRONT DOOR GLASS CHROME MOULDING <i>new</i>	1	\$ 168.00	\$ 168.00
19	FRONT DOOR WING MIRROR <i>Dented</i>	1	\$ 824.00	\$ 824.00
20	FRONT DOOR WING MIRROR COVER <i>new</i>	1	\$ 101.00	\$ 101.00

TOTAL PRICE: \$ 8,524.00

LESS 10% \$ 852.40

SUB TOTAL PRICE: \$ 7,671.60

6065

5458.50

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR FENDER SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR FENDER ARC GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR WHEEL RIM <i>new</i>	1	\$ 880.00	\$ 880.00
5	REAR TYRE <i>new</i>	1	\$ 250.00	\$ 250.00
6	REAR DOOR LOWER PROTECTOR CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
7	REAR DOOR GLASS SOLAR FILM <i>new</i>	1	\$ 200.00	\$ 200.00
8	REAR DOOR BLACK TAPE <i>new</i>	1	\$ 60.00	\$ 60.00
9	REAR DOOR VISOR <i>new</i>	1	\$ 100.00	\$ 100.00
10	FRONT DOOR LOWER PROTECTOR CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
11	FRONT DOOR GLASS SOLAR FILM <i>new</i>	1	\$ 200.00	\$ 200.00
12	FRONT DOOR BLACK TAPE <i>new</i>	1	\$ 60.00	\$ 60.00

13	FRONT DOOR VISOR	1	\$ 100.00	\$ 100.00
			TOTAL :	\$ 2,020.00

970

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	800	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	40	
5	TO TRANSFER FRONT & REAR DOOR FITTINGS	\$ 300.00	120	
6	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
7	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	
		TOTAL:	\$ 3,550.00	

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,691.60

TOTAL LABOUR COST: \$ 3,550.00

TOTAL REPAIR COST: \$ 13,241.60

1720

total: 8148.50

2/s: 6.5k

06 Days

6.5k

\$ 6.5k

L/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: