

First Motor

BLK 3006 UBI ROAD 1 #01-398 SINGAPORE 408700

TEL: 67431911 / 67448333 FAX NO: 67458131

RCB REG NO: 28964400C

EMAIL: first_motor_sg@yahoo.com

Date:

Ref no:

Veh No:

Model:

JVM 2290
LC 135

S/N	Description	Cost
1	MIRROR SET	50 wt
2	BRAKE LEVER	20 wt
3	HANDLE BAR BALANCE	22 wt
4	HANDLE BAR	75 bt
5	FOK ASSY N UNDER BRACKET ASSY	380 bt
6	STEERING CON ASSY	80 neu
7	FRONT COVER COWLING	45 dis
8	REAR COVER COWLING	45 dis
9	RIGHT SIDE FEARING SET	110 mis
10	LEFT SIDE FEARING SET	110 mis
11	HEAD LAMP SET	48 wt
12	WHEEL FRONT	210 bt
13	DIS ROTOR	110 bt
14	WHEEL SHAFT + nut	22 bt
15	RADIATOR ASSY	350 bt
16	LOWER COWLING ASSY	60 dis
17	METER COVER ASSY	45 mis
18	FOOT REST BAR	30 dis
19	FOOT BRAKE PADDLE	28 bt

First Motor

BLK 3006 UBI ROAD 1 #01-398 SINGAPORE 408700
 TEL: 67431911 / 67448333 FAX NO: 67458131
 RCB REG NO: 28964400C
 EMAIL: first_motor_sg@yahoo.com

Date:
 Ref no:
 Veh No: JUM 2290
 Model: LC 135

S/N	Description	Cost
20	EXHAUST PIPE GUARD 3pc.	90 cut
21	BASKET.	40 cut 150
22	CHASSIS REPAIR SN	380 R 1200
23	Front tyre 70/80/17 SN	70 cut ✓
5		
6	Parts 1970	
7	10/- 1773	
8	210	
9	270	
10	2253	
	1551800 Total parts & repair	2350
	03days	
	* /	
	Total	
	Labour & Misc.	200
	Labour Charge	300
	Towing From Accident Compensate Transport Fee	70 ✓
	Grand Total	2720

270

LKK Auto Centre

The Repairer of a motor vehicle is authorised to sign this invoice only if the following conditions are met:

- To repair the vehicle in accordance with the manufacturer's instructions.
- To display the signed invoice during resurvey.
- Parts price to be shown in the invoice.
- Third party liability cover is a "Without Fault" cover.
- No illegal modification is allowed.
- Supplementary work is subject to inspection and approval by the insurance company.

Authorised signature

Acknowledged by Repairer

Signature: _____

Date: _____

Tan Jiah 77495749 / 62563561
 3/10/24 0515pm
 Receiving new items
 Tan Jiah & Lkhamp.cn
 30/10/24

