## **Performance Motors Limited**



		FACSIMILE MES	SAGE	
DATE	20-11-24	TIME		
INS	UOI	FAX NO		_
		NO OF PAGES	1	_
ATTN	QRM Eric	_		
		FAX NO		
MCA	Jack Ng	FAX NO		
		TEL NO	6474 3229	200/00-
<u> </u>	f the fax is not received	in order, please do call (	CSA. Thank you	
Dear S			,	
	mentary repair for BMW	' <b>Y</b> 1		
	Registration No.	SKS1223L	•	
	Chassis No.	WBA32AA0005T16462	•	
Cunni	ementary Parts to rep	laced YES Refer	to attachment	
Suppli	ementary Parts to rep		to attachment	
		NO		200
LABOUR Description			QTY	Prices
TO REPLACE EXHAUST TURBOCHARGER			1	
<u></u>			l l	\$1,062.00
		***************************************		\$1,062.00
<b> </b>				\$1,062.00
				\$1,062.00
				\$1,062.00
				\$1,062.00
				\$1,062.00
				\$1,062.00
				\$1,062.00
				\$1,062.00
				\$1,062.00

Total =>

\$1,062.00