



## Supplementary

Estimate No. : **b1 71379**  
Date Estimated : **02/10/2024**  
Prepared By : **Jack Ng Guo Ming**

Page No. :

**- ESTIMATE REPAIR FOR -**

**Chua Guo Wei, Kent (Cai Guowei)**  
**Apt Blk 80C Telok Blangah Street 31**  
**#24-129**

**Singapore 103080**

**- ACCOUNT - 115**

**United Overseas Insurance Ltd**  
**146 Robinson Road**  
**#02-01 UOI Building**  
**Singapore 068909**

| REGN. NO. | CHASSI S NO.      | REGN. DATE | MODEL        | M LEAGE |
|-----------|-------------------|------------|--------------|---------|
| SKS1223L  | WBA32AA0005T16462 | 29/03/2021 | X1 sDrive18i | 33279   |

| DESCRIPTION                                                                                                                                        | ORIGINAL PRICE | DISC. % | NETT     |
|----------------------------------------------------------------------------------------------------------------------------------------------------|----------------|---------|----------|
| * To replace exhaust turbo charger with lubrications include calibration and adjustment of boost in accordance with BMW specifications             | 531.00         |         | 531.00 / |
| * To replace charge air cooler include conducting checks for leak and function                                                                     | 531.00         |         | 531.00 / |
| * To remove and reconnect all electrical components, control units, wiring systems in the engine bay include conducting checks for proper function | 531.00         |         | 531.00 / |

| DESCRIPTION                         | UNIT PRICE | QTY  | DISC. % | NETT              |
|-------------------------------------|------------|------|---------|-------------------|
| # ASA BOLT M10X65                   | 6.15       | 4.00 | 0.00    | 24.60 / Nec       |
| # O-RING                            | 3.30       | 2.00 | 0.00    | 6.60 / Nec        |
| # SEAL AIR INTAKE SYSTEM            | 17.05      | 3.00 | 0.00    | 51.15 / Nec       |
| # PROFILE GASKET                    | 17.05      | 1.00 | 0.00    | 17.05 / Nec       |
| # EXHAUST TURBOCHARGER              | 4,366.35   | 1.00 | 0.00    | 4,366.35 / Jammed |
| # GASKET RING                       | 12.75      | 3.00 | 0.00    | 38.25 / Nec       |
| # PIPE EXPANSION TANK CYLINDER HEAD | 63.50      | 1.00 | 0.00    | 63.50 / Nec       |

**Performance Motors Limited.**

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269  
Co Reg No. 197401559W





## Supplementary

|                                        |        |       |      |                  |
|----------------------------------------|--------|-------|------|------------------|
| # GASKET RING                          | 33.25  | 1.00  | 0.00 | 33.25 / nec      |
| # V BAND CLAMP                         | 47.55  | 1.00  | 0.00 | 47.55 / nec      |
| # SET OF SCREW PLUGS (7DCT300)         | 24.85  | 1.00  | 0.00 | 24.85 / Nec      |
| # EXPANDING RIVET BLACK                | 1.50   | 15.00 | 0.00 | 22.50 / Nec      |
| # DUMMY CONNECTOR 2 POL                | 4.00   | 1.00  | 0.00 | 4.00 / Nec       |
| # COIL SPRING CARTRIDGE                | 279.50 | 1.00  | 0.00 | 279.50 / Shorted |
| # (S/L) ANTIFR./CORROS. INHIBITOR 1.5L | 26.20  | 2.00  | 0.00 | 52.40 / Nec      |
| # (S/L)TURBOCHARGER ADDITIVE PETROL M  | 44.25  | 1.00  | 0.00 | 44.25 / Nec      |

### # SUPPLEMENTARY ITEMS

|                                     |          |
|-------------------------------------|----------|
| Total Labour :                      | 1,593.00 |
| Total Parts :                       | 5,075.80 |
| Total Labour & Parts (before GST) : | 6,668.80 |