

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT
SINGAPORE 417883

TO	: INDIA	DATE	: 25/6/2024
VEHICLE NO	: SNM2128T		
VEHICLE MODEL	: MAZDA 3 HYBRID		Veron.
CHASSIS NO	: JM6BP2SAAP1153540		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Distorted</i>	1	\$ 977.00	\$ 977.00
2	REAR BUMPER CENTRE BRACKET <i>new</i>	1	\$ 40.00	\$ 40.00
3	REAR BUMPER END SEAL COVER <i>Distorted</i>	1	\$ 68.00	\$ 68.00
4	REAR BUMPER INNER SIDE BRACKET <i>new</i>	1	\$ 41.00	\$ 41.00
5	REAR BUMPER LOWER BRACKET <i>new</i>	1	\$ 105.00	\$ 105.00
6	REAR BUMPER LOWER INNER BRACKET <i>new</i>	1	\$ 93.00	\$ 93.00
7	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 98.00	\$ 98.00
8	REAR BUMPER REINFORCEMENT <i>Distorted</i>	1	\$ 547.00	\$ 547.00
9	REAR BUMPER REVERSE SENSOR <i>1 piece damaged</i>	2	\$ 190.00	\$ 380.00
10	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	\$ 46.00	\$ 184.00
11	REAR BUMPER REVERSE SENSOR WIRE HARNESS <i>new</i>	1	\$ 508.00	\$ 508.00
12	REAR BUMPER SCREW HOLDER <i>new</i>	2	\$ 42.00	\$ 84.00
13	REAR BUMPER SIDE BRACKET <i>new</i>	2	\$ 38.00	\$ 76.00
14	REAR BUMPER SIDE BRACKET RIVET <i>new</i>	4	\$ 6.00	\$ 24.00
15	REAR BUMPER SIDE HOLDER <i>new</i>	1	\$ 69.00	\$ 69.00
16	REAR BUMPER TOW COVER <i>new</i>	1	\$ 35.00	\$ 35.00
17	REAR BUMPER UNDERCOVER <i>new</i>	1	\$ 99.00	\$ 99.00
18	REAR BUMPER CHASSIS MEMBER TOP PANEL <i>new</i>	1	\$ 296.00	\$ 296.00
19	REAR END PANEL <i>Distorted</i>	1	\$ 691.00	\$ 691.00
20	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 105.00	\$ 105.00
21	REAR END PANEL ANTENNA SENSOR <i>new</i>	1	\$ 98.00	\$ 98.00
22	TAILLAMP <i>new</i>	1	\$ 903.00	\$ 903.00
23	TAILLAMP PANEL <i>new</i>	1	\$ 375.00	\$ 375.00
24	REAR FENDER <i>new</i>	1	\$ 1,643.00	\$ 1,643.00
25	REAR FENDER INNER TRIM COVER <i>Distorted</i>	1	\$ 769.00	\$ 769.00
26	REAR FENDER INNER SHIELD <i>new</i>	1	\$ 139.00	\$ 139.00
27	REAR FENDER AIR VENT <i>Distorted</i>	1	\$ 88.00	\$ 88.00
28	REAR FENDER AIR VENT PANEL <i>Distorted</i>	1	\$ 148.00	\$ 148.00
29	REAR WINDSCREEN MOULDING <i>new</i>	1	\$ 109.00	\$ 109.00
30	SPARE TYRE PANEL SIDE SPONGE <i>new</i>	1	\$ 245.00	\$ 245.00
31	SPARE TYRE PANEL TOP COVER <i>new</i>	1	\$ 671.00	\$ 671.00
32	SPARE TYRE SIDE PANEL <i>new</i>	1	\$ 169.00	\$ 169.00
33	REAR HORN <i>new</i>	1	\$ 99.00	\$ 99.00
34	REAR HORN BRACKET <i>new</i>	1	\$ 28.00	\$ 28.00
35	REAR EXHAUST PIPE <i>new</i>	1	\$ 1,299.00	\$ 1,299.00
36	REAR EXHAUST PIPE MOUNTING <i>new</i>	1	\$ 39.00	\$ 39.00
37	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 35.00	\$ 35.00
38	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$ 129.00	\$ 129.00

TOTAL PRICE:

\$ 11,506.00

Spue Tyre Panel Side Tray. 2820
Distorted

5267
4213.60

LESS 20% \$ 2,301.20
SUB TOTAL PRICE: \$ 9,204.80

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REARBUMPER UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
3	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
5	REAR FENDER SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
6	REAR FENDER INNER TRIM CLIPS <i>new</i>	1 SETS	\$ 30.00	\$ 30.00
7	REAR FENDER INNER SHIELD CLIPS <i>new</i>	1 SETS	\$ 30.00	\$ 30.00
8	REAR WINDSCREEN SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
9	SPARE TYRE PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00

140

TOTAL : \$ 370.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,400.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>800</i>	
3	WIRING CHECK	\$ 50.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>60</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE UPHOLSTERY	\$ 150.00	<i>60</i>	
7	TO REMOVE REAR WINDSCREEN	\$ 180.00	<i>+</i>	
8	TO REMOVE EXHAUST PIPE	\$ 150.00	<i>+</i>	
9	TO REMOVE FUEL TANK	\$ 150.00	<i>+</i>	

TOTAL: \$ 3,530.00

1800

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,574.80
TOTAL LABOUR COST: \$ 3,530.00
TOTAL REPAIR COST: \$ 13,104.80

total: 6753.60

4/s: 49K.

06 Days

4.9K.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____