

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

Daphne

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2400391
Date: 07 Oct 2024
Veh Reg No: SMA1683M
Make/Model: TOYOTA VIOS E (AUTO)
Chasis No: MR2B23F3101121547
Reg. Date: 30/05/2018
Your Ref No: GBJ4310C

Claim Type: Third Party
Accident Date: 03/10/2024
TP Veh Reg No: GBJ4310C

Estimate Repair Cost to Vehicle No :SMA1683M

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC BOOT LID <i>Dented</i>	1327.95 ✓	
2	2 PCS BOOT LID HINGE <i>new</i>	182.40 +	
3	1 PC BOOT LID LOGO	66.90 ✓	
4	1 PC BOOT LID "VIOS" EMBLEM <i>new</i>	49.40 ✓	
5	1 PC BOOT LID "E" EMBLEM	38.40 ✓	
6	1 PC BOOT LID LOCK <i>new</i>	432.50 ✓	360
7	1 PC BOOT LID LOCK CHECKER <i>new</i>	39.40 +	
8	1 PC BOOT LID TRIM <i>new</i>	352.00 +	
9	1 PC BOOT LID RUBBER <i>new</i>	190.10 ✓	
10	1 PC BOOT LID LAMP LH <i>new</i>	466.90 ✓	380
11	1 PC BOOT LID LAMP RH <i>new</i>	466.90 ✓	380
12	1 PC TAIL LAMP LH <i>new</i>	687.90 ✓	450
13	1 PC TAIL LAMP - RH <i>new</i>	687.90 ✓	453
14	1 PC REAR BUMPER <i>Dented</i>	670.90 ✓	
15	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	360.10 ✓	
16	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	335.80 +	
17	2 PCS REAR BUMPER RETAINER (SMALL)	130.20 +	
18	1 PC REAR BUMPER REFLECTOR - LH <i>new</i>	191.80 +	
19	1 PC REAR BUMPER REFLECTOR - RH <i>new</i>	191.80 +	
20	1 PC REAR PANEL <i>Dented</i>	803.20 ✓	
21	1 PC REAR PANEL TRIM <i>Dented</i>	301.50 ✓	
22	1 PC REAR FENDER TRIM LH <i>new</i>	356.40 +	
	<i>1 pc rear Antenna sensor new</i>	7.855.30	
	<i>new</i>	1.963.83	5.891.53
Special Net			
23	1 PC BOOT LID NUMBER '610' STICKER <i>new</i>	35.00 ✓	
24	1 SET BOOTLID TRIM CLIPS <i>new</i>	40.00 +	
25	2 PCS "L" PLATE BRACKET <i>new</i>	70.00 ✓	50
26	1 SET REAR BUMPER STICKER <i>new</i>	280.00 ✓	220
27	1 SET REAR BUMPER CLIPS <i>new</i>	60.00 ✓	30

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2400391
Date: 07 Oct 2024
Veh Reg No: SMA1683M
Make/Model: TOYOTA VIOS E (AUTO)
Chasis No: MR2B23F3101121547
Reg. Date: 30/05/2018
Your Ref No: GBJ4310C

Claim Type: Third Party
Accident Date: 03/10/2024
TP Veh Reg No: GBJ4310C

Estimate Repair Cost to Vehicle No :SMA1683M

Quantity	Description	List Price	Amount
		SS	SS
28	1 PC REAR NUMBER PLATE <i>the m</i>	50.00 <i>x</i>	
29	1 SET REAR PANEL TRIM CLIPS <i>m</i>	40.00 <i>20</i>	
30	1 SET REAR FENDER TRIM CLIPS LH <i>2nd m</i>	60.00 <i>x</i>	
31	1 SET REAR FENDER TRIM CLIPS RH	60.00 <i>x</i>	
		695.00	695.00
	Labour		
32	1 TO CHECK WIRING	50.00 <i>30</i>	
33	1 TO REPLACE STICKERS	80.00 <i>x</i>	
34	1 TO REMOVE AND REFIT REAR INNER TRIM	100.00 <i>40</i>	
35	1 TO SPRAY ANTI RUST	60.00 <i>40</i>	
36	1 (REAR) TO SPRAY PAINTING	1,000.00 <i>600</i>	
37	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 <i>700</i>	
		2,290.00	2,290.00
	Total		S\$ 8,876.53
	Add GST @ 9%		798.89
	Total Amount Payable		S\$ 9,675.42

TOTAL: SINGAPORE DOLLAR NINE THOUSAND SIX HUNDRED SEVENTY FIVE AND CENTS FORTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer
Signature:
Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Admin
4/s 07/10/24
06 Days
Total 6587.88
4/s 15250
(250)