

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration NO: 201400246D
GST Reg. NO: 201400246D

TP ALG.
Yan.

2-Oct-24

Our ref : TP/5463/24

Lim Hwee Yang

RE : Estimate cost for vehicle no : SJM 2756C

1 pc	bootlid <i>Dented</i>	\$	✓ 766.70
1 pc	bootlid lock <i>new</i>		✓ 139.00
1 pc	bootlid w/strip <i>cut</i>		✓ 200.00
1 pc	logo emblem <i>new</i>		✓ 72.20
1 pc	Vios emblem <i>new</i>		✓ 48.00
1 pc	bootlid outer garnish <i>new</i>		+ 270.00
2 pcs	taillamp <i>cracked</i>	3883.60	✓ 620.00
2 pcs	taillamp seal <i>new</i>		✓ 56.00
2 pcs	taillamp clips <i>new</i>	2912.70	+ 21.60
1 pc	rear bumper <i>Delund</i>		✓ 595.70
2 pcs	rear bumper retainer long <i>new</i>		+ 200.00
2 pcs	rear bumper retainer short <i>new</i>		+ 120.00
2 pcs	rear bumper reflectors <i>RH cracked</i>		125 250.00
2 pcs	rear bumper bracket <i>new</i>		+ 140.00
6 pcs	rear bumper clips <i>new</i>		✓ 30.00
1 pc	end panel <i>Dented</i>		✓ 745.00
1 pc	end apnel inner garnish <i>Delund</i>		✓ 235.00
1 pc	spare tyre panel <i>Repair</i>		+ 755.00
1 pc	spare tyre cardboard centre <i>cracked</i>		✓ 145.00
2 pcs	spare tyre cardboard rh lh <i>Delund</i>		✓ 106.00
1 pc	exhaust pipe <i>Repair</i>		+ 635.00
			6150.20
less 25%			1537.55
			4612.65
1 pc	rear no plate <i>new</i>	snett	+ 40.00
1 pc	reverse sensor <i>new</i>	240	200 250.00
Panel beating.			1400.00 1700
Spray painting.			1200.00 1000
Rust proofing.			80.00 60
Upholstery.			120.00 60
Wiring.			30.00 ✓
Remove & refit reverse sensor.			120.00 50
			9390.20

Adrian C.
2/8 2024

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration NO: 201400246D
GST Reg. NO: 201400246D

RE : Estimate cost for vehicle no : SJM 2756C

Bal brought forward:

Remove & refit exhaust pipe.

Plus 9% GST

\$	9,390.20
	<u>120.00</u> ⁶⁰
	9510.20
	<u>855.91</u>
	10,366.11

SD : ten thousand three hundred sixty-six & cents eleven only.

Adnan L
H/S 02/10/24.
07 Days -

Total: 5512.70
H/S: 4 HK

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: