

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

4 Oct 2024

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #09-16
AIG Building
Singapore 079120

not Authorized
for
Moray
4/10/24
H/c #8000
Whph/Akery
6 days

THIRD PARTY CLAIM

OWNER NAME : LIU WEIJIE
VEHICLE REG NO : SML6261G
DATE OF ACCIDENT : 3 OCT 2024
PLACE OF ACCIDENT : ALEXANDRA ROAD/QUEENSWAY ROAD
INVOLVING VEH NO : SMF590C

We append herewith our estimate for Vehicle SML6261G as follows:

Materials Required

1 pc	Front Bumper	cur/70m	1558.00	SS\$1,721.90	/
1 pc	Front Bumper Retainer RH	n		SS\$ 124.80	X
1 set 10 pcs	Front Bumper Clips	ku		SS\$ 65.00	305/W
1 pc	Front Fender RH	oo Bent		SS\$ 587.20	/
1 pc	Front Door RH	R		SS\$1,310.10	X
1 pc	Front Door Outer Handle RH	cu		SS\$ 285.50	/
1 pc	Front Door Side Mirror RH	Che		SS\$ 526.60	/
1 pc	Rear Fender RH	R		SS\$1,005.20	X
1 pc	Front Cross Member	Bent/Twi	2164.00	SS\$2,165.80	/
1 pc	Front lower Arm RH	Bent/Twi		SS\$ 614.30	/
1 pc	Front Lower Arm LH	Bent/Twi	614.30	SS\$ 753.10	/
1 pc	Front Knuckle Arm LH	Bent	534	SS\$ 651.20	/
1 pc	Front Knuckle Arm Bearing LH	Dange	650	SS\$ 898.60	/
1 pc	Front Tie Rod LH	su		SS\$ 269.30	X
1 pc	Front Rack End LH	n		SS\$ 377.60	X
1 pc	Rear Knuckle Arm LH	n		SS\$1,610.20	X
1 pc	Rear Knuckle Arm Bearing LH	n		SS\$ 413.50	X
2 pcs	Front Tyre Rims RH/LH	cur/Bent		SS\$1,900.00SN	1200 S/W
2 pcs	Front Tyre RH/LH	n/500T	4P280	SS\$ 750.00SN	502 1PC 140S/W
2 pcs	Rear Tyre Rims RH/LH	cu		SS\$1,900.00SN	1PC 600 S/W
				SS\$17,929.90	

1202

SUPER-ZEE MOTOR SERVICE

BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195 TEL: 6383 1913 FAX: 6383 9565
EMAIL: superzeemotor@gmail.com

SML6261G

Page 2

Labour Charges

Towing Charge	S\$ 100.00	✓
To dismantle & replace damaged body parts and panelbeating	S\$ 950.00	580
To dismantle & replace undercarriage parts	S\$ 550.00	300
To putty, apply primer & spraypaint affected portion	S\$1,200.00	880
To apply rustproofing on repaired, replaced panel	S\$ 200.00	30
To check electrical wiring functions	S\$ 80.00	20
Computerised Wheel Alignment	S\$ 120.00	100

	S\$21,129.90	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPER-ZEE MOTOR SERVICE

P- 7533-90
202
P- 6027-12
S.N 1970
L- 2010
10007-12
Book