



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100105/Eqp3m4
(BUDGET DIRECT INSURANCE)	Date:	28/10/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMU 5814X	Veh. Inspected	SNK 4246H
Policy No.	P11098082R00	Coverage	0
Claim No.	C10032072/CY	Excess	\$0.00
Assign From	CALEEN YIT	Assign Date	04/10/2024

2. Vehicle Details

Make & Model	TOYOTA ALPHARD	C.C	2493
Engine No.	2AR2845020	Year of Reg.	13/04/2023
Chassis No.	AGH300443199	Colour	BLACK
Odometer	106102 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50R18	GRENLANDER	5
L/H Front Tyre	235/50R18	GRENLANDER	5
R/H Rear Tyre	235/50R18	GRENLANDER	5
L/H Rear Tyre	235/50R18	GRENLANDER	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/10/2024	Inspection Date	04/10/2024
Survey held at	KY AUTO PTE LTD 25 KAKI BUKIT ROAD 4 #05-23 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days