

KY AUTO PTE LTD

25 Kaki Bukit Road 4 #05-23 Synergy Building S417800

M (65) 9807 3304 Mr. Yap

F (65)

Email : kyautosg@gmail.com

Date: 03/10/2024

D.O.A 02/10/2024

SNK4246H - Toyota Alphard

Damaged Area: Rear Portion

Parts / Material :

1 Rear bumper	/ BR	\$1,980.90	1487 /
2 Rear bumper side retainers LH & RH @ SGD 215.60	? BR 112 x 2	\$431.20	224 /
3 Rear bumper bracket LH & RH @ SGD 165.30	X nn	\$431.20	
4 Rear bumper reflector LH @ \$120.30	X nn	\$240.60	
5 Rear bumper pdc sensor set	? 290 x 2 Shorted	\$1,455.60	580 /
6 Rear bumper tow garnish LH	DEF 50 x 2	\$110.60	100 /
7 Rear bumper side o/s LH & RH @ \$155.70	X nn	\$311.40	
8 Rear bumper clips	/ nrc	\$80.00	30 /
9 Rear end panel outer	/ DD (take photo)	\$1,557.80	781 /
10 Rear end panel top garnish	/ CRV	\$428.60	225 /
11 Rear end panel top garnish clips	/ nrc	\$80.00	30 /
12 Rear Fender LH	/ nn	\$3,860.80	
13 Rear Fender Liner LH	X nn	\$386.40	
14 Tailgate	/ DD	\$3,556.80	2080 /
15 Tailgate logo (Alphard, e-power, synergy drive)	X nn	\$685.60	
16 Tailgate weather strip	/ TH	\$920.50	324 /
17 Tailgate logo	/ nrc	\$558.70	80 /
18 Tailgate switch	X nn	\$539.60	
19 Rear Fender Outer Cover LH	X nn	\$515.20	
20 Tailgate Lock	? 180 Jammed	\$628.40	480 /
21 Tailgate trim	? 650 / BR	\$18,759.90	
Parts:			

Special Net Items:

Miscellaneous Item

Arcylic Sealant (windscreen repair)

\$120.00 30

\$100.00 40

Total S/N P \$200.00

70

70

Labour:

To Remove & Renew Rear Affected Accident Areas

\$2,500.00 1200

To Putty, Spray Paint on Rear Affected Accident Areas	\$2,500.00	800
To conduct computerised wheel alignment	\$150.00	X
To remove and reinstall wire harness. Check according to damage.	\$200.00	X
To Rust proof affected area	\$200.00	30
To remove and reinstall Inner Trim, compartment	\$200.00	80
To Conduct & reset ECU diagnostic programme	\$450.00	X
Total Labor	\$6,200.00	2110

TOTAL PARTS : \$18,759.90
TOTAL S/N PARTS: \$200.00
TOTAL LABOUR : \$6,200.00
TOTAL REPAIR COST : \$25,159.90

7633.25

L/S - 6106.60
= 6100

Steve (LKK)
 4/10/24, 3:30pm
 m IL
 L/S
 LK IL
 7 days

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: ..

Date: