



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24100120/Kvh3e2
300 BEACH ROAD	Date:	22/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- OWN DAMAGE CLAIM

Insured Veh.	-	Veh. Inspected	GBH 3919P
Policy No.	Z23VC05020890	Coverage	0
Claim No.	23/24/24/VC05/029893	Excess	\$600.00
Assign From	ERIC WOO	Assign Date	07/10/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA (M)	C.C	2982
Engine No.	1KD2621058	Year of Reg.	21/05/2018
Chassis No.	KDY2318025287	Colour	SILVER
Odometer	- KM	Steering	JAMMED
Brakes	JAMMED	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195 R15X8	MAXXIS	9
L/H Front Tyre	195 R15X8	MAXXIS	9
R/H Rear Tyre	195 R15X8 (D)	MAXXIS	1/1
L/H Rear Tyre	195 R15X8 (D)	MAXXIS	1/1

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY

DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/09/2024	Inspection Date	07/10/2024
Survey held at	K KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE MARKET VALUE IS S\$47,000.00(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 24 Working Days