

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En	Automobile
MS	UNITED OVERSE	AS INSURANCE LTD	Ref:	CS/UOI24100126/Rqh3e2
	146 ROBINSON R	OAD	Date:	27/11/2024
	#02-01 UOI BUILD	ING SINGAPORE 068909	Code:	UOI2
1.	Policy Particulars :- OWN DAMAGE CLAIM			
	Insured Veh.	-	Veh. Inspected	SMQ 6315J
	Policy No.	DHOM123000142200	Coverage	0
	Claim No.	M12D00032410	Excess	\$500.00
	Assign From	TAN WEI YIN	Assign Date	07/10/2024
2.		Vehic	cle Details	
	Make & Model	B.M.W. 216I	C.C	1499
	Engine No.	37105771B38A15A	Year of Reg.	27/11/2019
	Chassis No.	WBA6V120905P09878	Colour	BLUE
	Odometer	87135 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3.		Condition	ons of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	205/55 R17	BRIDGESTONE	6
	L/H Front Tyre	205/55 R17	BRIDGESTONE	6
	R/H Rear Tyre	205/55 R17	BRIDGESTONE	6
	L/H Rear Tyre	205/55 R17	BRIDGESTONE	6
4.		Description	on of Damages	
HE	VEHICLE SUSTAI	NED DAMAGES AT THE FRONT N/S	PORTION.	
DAM	IAGES SEE DETAI	LS.		
5.	General Information			
	Accident Date	04/10/2024	Inspection Date	09/10/2024
	Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks				
		E IS S\$119,000.00(EST. AVERAGE) O YOUR INSTRUCTIONS, WE HAVE A	AUTHORISED REPAIR	RS
<i>)</i> ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,				

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days