



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

Fathi
3004

Customer :

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET

#04-00 & #06-00

IOB BUILDING

SINGAPORE 049711

ATTN: INDIA INTERNATIONAL INSURANCE P.L.

VEHICLE NO. : FP2012Y

MAKE/MODEL : HON / CB400S5

QUOTATION

NO. : 46858

DATE : 22/06/2024

CLAIM NO. : 12517


POLICY NO. : MC/00892316/03

FROM : STEPHANIE

not Authorized
M/L
meraj
25/6/24
1/5/9
Stephanie
3 days

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 28218 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$232.00	232.00
2	BOX REAR (GIVI) E450N SIMPLY II P/N: 80092 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$279.00	279.00
3	GASKET EXHAUST PIPE (REAR) P/N: 29402 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00
4	GRIP HANDLE SET ZEDGE - (REPORTED BY MECHANIC)	REPLACE	1.00	\$46.00	46.00
5	GUARD ENGINE CHROME - 2 POINTS P/N: 36385 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$186.00	186.00
6	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	Supply/Install	7.00	\$85.00	595.00
7	LAMP SIGNAL FRONT RH P/N: 17757 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$59.00	59.00
8	METER OBU (12V) TYPE B P/N: 80693 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$465.00	465.00
9	MIRROR RH P/N: 20463 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$129.00	129.00



S/N	Description	Action	Qty	Unit Price	Amount
10	MUFFLER (REAR) P/N: 36920 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,282.00	1,282.00
11	PROTECTOR EXHAUST P/N: 44615 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$93.00	93.00
12	SPEEDOMETER ASSY - (REPORTED BY MECHANIC) - PARTS DISCONTINUED	REPLACE	1.00	\$500.00	500.00

SUB TOTAL

\$3,880.00

GST @ 9 %

\$349.20

GRAND TOTAL (SGD)

\$4,229.20

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

