

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	08 Oct 2024 14:06	Clim Dtl Modified	Claimant's Name: -> STS SUPPORT PTE. LTD.	[A] HuehYin
2	08 Oct 2024 14:06	Clim Veh Model Changed	(207781) TOYOTA HIACE 2.0 (A).	[A] HuehYin
3	08 Oct 2024 14:06	Clim Created	Reg No: GBH8975T. Acct Date: 2024/10/03. Claim Type: TP. Insurer: ECICS Limited (HQ). Workshop: SPEEDWERKZ PTE LTD (Autobay) (HQ)	[A] HuehYin
4	08 Oct 2024 14:06	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] HuehYin
5	08 Oct 2024 14:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2024/10/17	[A] HuehYin
6	08 Oct 2024 14:06	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] HuehYin
7	08 Oct 2024 14:07	Adj Adjuster Assigned	[None] -> MARCUS CHUA	[A] HuehYin
8	24 Oct 2024 13:05	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
9	24 Oct 2024 13:05	Ins Email Updated	[None] -> [NOEMAIL@EMAIL.COM]	[A] Elaine Kuan Hwa Meen
10	24 Oct 2024 13:05	Clim Dtl Modified	Insured Name: -> -. Insured ID: -> -. Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
11	24 Oct 2024 13:05	Clim Dtl Modified	JPJ Reg. Date: -> 2018/10/29.	[A] Elaine Kuan Hwa Meen
12	24 Oct 2024 13:05	Clim Details Notified		[A] Elaine Kuan Hwa Meen
13	24 Oct 2024 14:33	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2024/10/17	[A] SHIAU CHAN
14	24 Oct 2024 14:33	Adj Mandate Request	Cur.Req:13080.00:KINDLY APPROVE REPAIR COST.	[A] SHIAU CHAN
15	25 Oct 2024 18:49	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2024/10/17. Mandate Remarks: Upload photo showing right headlamp damaged	[I] Crystabelle Tan
16	25 Oct 2024 18:49	Adj Mandate Set	Maintained:Upload photo showing right headlamp damaged	[I] Crystabelle Tan
17	28 Oct 2024 09:20	Adj Mandate Request	Cur.Req:13080.00:Please refer to damage photos 174 to 177 for right headlamp via Merimen.	[A] SHIAU CHAN
18	28 Oct 2024 17:30	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2024/10/17. Mandate Remarks: Upload photo showing right headlamp damaged	[I] Crystabelle Tan
19	28 Oct 2024 17:30	Adj Mandate Set	Approved:12000.00:Upload photo showing right headlamp damaged	[I] Crystabelle Tan

Date From



Date To



Audit Type

ACTIVITY
No record

Merimen Billing for this case - Transaction History								
Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
3259822	24 Oct 2024 13:05:12	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	GBH8975T	SKQ6442Z	12.00

