

HUA MENG SPRAY PAINTING WORKSHOP

1, KAKI BUKIT AVENUE 6, BLK C #01-61 / 01-34, SINGAPORE 417883

AUTOBAY @ KAKI BUKIT

TEL : 6747 8064 , 6746 5519 / 9666 9680 FAX : 6743 4896

ESTIMATE

TAMSIG
Veron

VEHICLE NO : SKS 4109 P

MAKE / MODEL : HONDA MOBILIO

CHASSIS NO : MRHDD4870FP000048

ACCIDENT DATE : 24.11.2024

NO	DESCRIPTION	QTY	AMOUNT (\$)
LIST ITEMS			
1	Rear windscreen rubber <i>new</i>	1	\$ 111.78 ✓
2	Rear tailgate <i>Dented</i>	1	\$ 1256.14 ✓
3	Rear tailgate hinge @ \$44.27 <i>3 new</i>	2	\$ 88.54 +
4	Rear tailgate shock absorber @ \$228.39 <i>2</i>	2	\$ 456.78 +
5	Rear tailgate upper lock <i>new</i>	1	\$ 254.49 ✓
6	Rear tailgate lower catch <i>3 new</i>	1	\$ 254.49 +
7	Rear tailgate inner board <i>3 new</i>	1	\$ 212.98 +
8	Rear tailgate weather strip <i>new</i>	1	\$ 111.20 ✓
9	Rear tailgate MOBILIO emblem <i>3 new</i>	1	\$ 40.48 ✓
10	Rear tailgate RS emblem <i>3 new</i>	1	\$ 40.02 ✓
11	Rear tailgate IVTEC emblem <i>3 new</i>	1	\$ 33.00 ✓
12	Rear end panel <i>new</i>	1	\$ 361.90 +
13	Rear end panel top garnish <i>Dented</i>	1	\$ 104.42 ✓
14	Rear bumper <i>Dented</i>	1	\$ 533.37 ✓
15	Rear bumper side holder @ \$45.42 <i>new</i>	2	\$ 90.84 +
16	Rear bumper lower moulding <i>new</i>	1	\$ 262.54 ✓
17	Rear bumper reflector @ \$ 37.37 <i>RH new</i>	2	\$ 74.74 37.37
18	Rear bumper reverse sensor <i>new</i>	2	\$ 380.00 +
19	Rear ethaust pipe <i>3 new</i>	1	\$ 857.67 +
20	Rear ethaust pipe chrome <i>3 new</i>	1	\$ 107.41 +
21	Rear bumper RH inner spong1 <i>new</i>	1	\$ 62.20 ✓
			\$ 2588.87
			LESS 20% DISC \$ 0
			TOTAL \$ 0.00

2588.87
2071091

LABOUR COST

1	To supply rear windscreen sealant	1	\$ 50.00 ✓
2	To supply rer end panel inner sealant <i>new</i>	1	\$ 200.00 ✓
3	Remove + reinstall rear windscreen <i>new</i>	1	\$ 150.00 120
4	Remove + reinstall reverse sensor	1	\$ 150.00 50
5	Remove + reinstall ethaust pipe	1	\$ 150.00 80
6	Remove + reinstall bootlid inner garnish	1	\$ 150.00 80
7	Remove, replace + repair consistent to the accident	1	\$ 1300.00 700
8	Respray painting the Repairer of the following:	1	\$ 1200.00 600
			TOTAL \$ 3350.00
			GRAND TOTAL \$ 3350.00

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

1680

GRAND TOTAL

\$

3350.00

blw 375109

h/s: 3K

3K

Adrian L

1/5 26/11/24 04 Days