



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWERSINGAPORE 048583 ATTN: ANDY SEAH			Ref: CS/LIP24100155/Anh3m4(N) Date: 16/05/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBK 7315P	Veh. Inspected	SLC 7081L
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS24/3098	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	07/10/2024
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 4DR 1.5 AT M-HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	JM6BP2SAAN1150852	Colour	GREY
	Odometer	48013 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45R18	BRIDGESTONE	6 mm
	L/H Front Tyre	215/45R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	215/45R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	215/45R18	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/10/2024	Inspection Date	08/10/2024
	Survey held at	SIN YU SIN WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-52 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)REGISTRATION DATE: 12 APR 2022 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	