

BLUWEL AUTOMOTIVE SERVICE PTE LTD
 1 KAKI BUKIT AVE 6 # 01-28/53/55/56
 SINGAPORE 417883 TEL :67452088

1/5 ~~4650~~
 6 days

Not Authorized
 dis
 means
 8/10/24
 Wahpho Henry

VEHICLE No: SKA 12E

1PC	REAR BUMPER UPPER	Dis	\$805.00	✓
1PC	REAR BUMPER CENTRE BLACK	Torn	\$790.00	✓
1PC	REAR BUMPER LOWER SILVER	Torn	\$275.00	✓
1PC	REAR BUMPER REFLECTOR N/S	one	\$86.00	✓
1PC	REAR BUMPER LOWER UNDER COVER	del/torn	\$390.00	✓
1PC	REAR BUMPER LOWER UNDER GARNISH	del/torn	\$331.00	✓
1PC	REAR BUMPER SIDE RETAINER N/S	one	\$45.00	✓
1PC	REAR BUMPER BEAM	11	\$496.00	X
1PC	REAR BUMPER LAMP N/S	one	\$285.00	✓
1PC	REAR BUMPER PDC SENSOR N/S	malfunction	\$220.00	✓
1PC	REAR BUMPER PDC SENSOR WIRE	one	\$292.00	X
1PC	REAR SIGNAL LAMP N/S	one	\$650.00	✓
1PC	REAR END PANEL OUTER	one/one	\$426.00	✓
1PC	TAILLAMP N/S	one	\$947.00	X
1PC	REAR FENDER OUTER PROTECTOR N/S	del/torn	\$288.00	✓
			\$6,326.00	
			LESS 10%	\$5,693.40

S.NETT

1SET	REAR BUMPER CLIPS	one	\$35.00	✓
1PC	REAR LICENCE PLATE	11	\$50.00	X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	40
TO DISMANTLE & REFIX REAR WINDSCREEN	\$100.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$100.00	30
TO DIAGNOSTIC & REPROGRAMME SYSTEM	\$250.00	80
LABOUR FOR PANEL BEATING	\$900.00	600
TO PUTTY & SPRAY PAINTING	\$1,180.00	800
TOTAL	\$8,558.40	

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To survey before/after spray painting
 • To display damaged parts, for survey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be restoraged and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P-4591
 102
 4131.90
 35
 1640
 5816.9
 202
 4653