

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
			Ref:	CS/INC24100165/Unh3m4	
IVIO	75 BRAS BASAH ROAD				
	INCOME CENTRE SINGAPORE 189557		Date:	23/10/2024	
			Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLZ 913L	Veh. Inspected	SJK 2113T	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1298463-002	Excess	\$0.00	
	Assign From	MARCUS XIAO	Assign Date	08/10/2024	
2.	2. Vehicle Details				
	Make & Model	HONDA JAZZ 1.5 (A)	C.C	1498	
	Engine No.	L15B31190955	Year of Reg.	19/06/2017	
	Chassis No.	JHMGK5850HX201322	Colour	BLACK	
	Odometer	150234 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/55R16	CONTINENTAL	6	
	L/H Front Tyre	185/55R16	CONTINENTAL	6	
	R/H Rear Tyre	185/55R16	CONTINENTAL	6	
	L/H Rear Tyre	185/55R16	CONTINENTAL	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	03/10/2024	Inspection Date	09/10/2024 (09:25)	
	Survey held at	BLUWEL AUTOMOTIVE SERVICE PL			
		BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE)			
	SINGAPORE 417883				
5a.					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days