

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS LIBERTY INSURANCE PTE LTD			Ref:	CS/LIP24100169/Unh3e2	
IVIO	ONE RAFFLES QUAY #25-01 NORTH TOWER		Date:	24/10/2024	
	SINGAPORE 048583				
			Code:	LIP	
1.					
	Insured Veh.	YQ 1147T	Veh. Inspected	YP 1532U	
	Policy No.	-	Coverage	0	
	Claim No.	IVS24/1928	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	08/10/2024	
2. Vehicle Details					
	Make & Model	MITSUBISHI CANTER FEB21 (M)	C.C	2998	
	Engine No.	4P10C00917	Year of Reg.	29/02/2016	
	Chassis No.	FEB21EA20221	Colour	WHITE	
	Odometer	356525 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3.	Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	195R15	AUSTONE	6	
	L/H Front Tyre	195R15	AUSTONE	6	
	R/H Rear Tyre	195R15 (D)	AUSTONE	6/6	
	L/H Rear Tyre	195R15 (D)	AUSTONE	6/6	
4.	Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND FRONT WINDSCREEN CRACKED.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	05/10/2024	Inspection Date	08/10/2024	
	Survey held at				
		1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT			
	SINGAPORE 417883				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					