

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SNL9182U	Date of Request	14.10.2024
Vehicle Model	TOYOTA SIENTA	Number of Days to Extend (If any)	2

S/N	PART DESCRIPTION		LIST PRICE
1	FRONT PARKING SENSOR WIRING HARNESS <i>snapped</i>		\$542.10 410.
2	FRONT AIR BAG SENSOR LH <i>not new</i>		\$342.50 X
3	REAR FENDER INNER TRIM RH <i>Not Nec</i>		\$848.50 X
4	REAR FENDER INNER TRIM LH <i>cracked</i>		\$848.50 ✓
5	REAR PARKING SENSOR HARNESS <i>not new</i>		\$533.20 X.
6	REAR TAILGATE MODULE AFTERMARKET <i>not new</i>		\$850.00 X.

1258.50
 Supplementary : 943.87.