

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

C5/111 24100178/Unp3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV**

To Inspect Vehicle No: SLA 74245

at Workshop m/s

of

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: 2,600

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$24k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA (REV) / REP. / 24 HRS

751d  
Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLA 74245

Yr Regn: 15/03/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel

c.c

1496

Colour: Blue

A/C:

Insured / Std / NI / NA

Sp. Reading: 133180

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU11110576

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 07/10/24

D.O.I. 10/10/24

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/10/24 15/1600 in hand Daud (Red. \$1624.08, 50%)

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 3

1)

☐

Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	751D
<b>Vehicle Details</b>	
Vehicle No.:	SLA7424S
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2024
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X A
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	L15B4030579
Chassis No.:	RU11110576
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,749.00
Original Registration Date:	15 Mar 2016
First Registration Date:	15 Mar 2016
Transfer Count:	1
Actual ARF Paid:	\$9,749.00 $\downarrow$ \$14
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Mar 2026
PARF Rebate Amount:	\$5,361.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	14 Mar 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$6,659.00
<b>Total Rebate Amount:</b>	<b>\$12,020.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 10 Oct 2024

OK



Honda Vezel 1.5A X

**\$24,800**

\$13,700 /yr

21-Mar-2016

(1yr 5mths COE left)

123,000 km



Honda Sensing

Instl. \$1,121

/mth

1,496 cc

1 Owner

Cheapest In The Market With Guaranteed Buyback At \$10,000 At End Of COE. Depreciation At \$9000+ Only. Rare 1 Owner With Low Mileage Proves Its Non Phv With Proofs. Best Mid Sized SUV. Spacious, Reliable And Low In Consumption And Maintenance. Accident In Original Paintwork Still Intact. Clean And Beautiful Interior. Sheltered Parked Daily. Sheltered Parked Daily. Non Smoker. Full In Hse/bank Loan

BuySafe

Posted 08-Oct-2024

☐ Compare


Honda Vezel

**\$34,800**

\$12,660 /yr

27-Dec-2016

(2yrs 2mths COE left)

98,000 km

1,496 cc



1.5A X

Instl. \$1,025

/mth

1 Owner

One of the most popular SUV in Singapore, experience the perfect blend of style, comfort, and efficiency with this stunning 1 owner, well-maintained unit. Spacious interior features a flexible seating arrangement and allows easy configuration to accommodate for passengers or cargo. Impressive fuel efficiency with safety features making it a reliable/popular choice. Contact us today for viewing!

Warranty

SG Car Choice Pte Ltd|Posted 07-Oct-2024

☐ Compare


Honda Vezel

**\$21,800**

\$13,100 /yr

04-Feb-2016

(1yr 3mths COE left)

80,000 km

1,496 cc



1.5A X

Instl. \$1,122

/mth

1 Owner

1 Owner, Excellent Condition And Well Kept By Previous Owner! Loan

Available! Trade In Welcome! Act Fast And Call Us Now To Fix An Appointment To View This Stunning Unit!

Zenith Automobile|Posted 07-Oct-2024

☐ Compare

## Handy Tools

View All

Loan Calculator



Used Car Depre Finder



Bidded Carplate



COE Renewal



Petrol Discount



My Shortlist


[Compare](#)

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3158/10/24

Your Ref:

Date: 8th OCT 2024

MR KOH YOK HUAT  
BLK 381A, #10-1529  
YISHUN RING RD,  
SINGAPORE 761381

*Not Authorised*  
*all*  
*merch*  
*10/10/24*  
*2/8 \$1600*  
*Excess \$600?*  
*Take the After 3 days*

Estimate cost of repair to HONDA VEZEL 1.5 (A) SUV - SLA 7424 S

1 pc front bumper	DD	\$ 947.30	✓
10 pcs front bumper clips	CS 3.90	✓ 39.00	✓
1 pc front bumper o/s side retainer	✓	29.50	X
1 pc front bumper o/s top retainer	✓	48.50	X
1 pc front o/s fender	✓	431.20	X
1 pc front o/s fender wheel garnish	✓	150.60	✓
10 pcs front o/s fender wheel garnish clips	CS 3.90	✓ 39.00	X
		\$ 1,685.10	
	Less 20%	\$ 337.02	
		\$ 1,348.08	

To wiring check up for affected wiring system.	50.00	20
To check & adjust front wheel alignment & balancing.	120.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front o/s fender, front bumper reinforcement & necessary parts, to weld, renew & align above parts.	650.00	300
To putty & respray painting on all affected accident parts.	700.00	500
To respray Tuff-Kote on all affected accident parts.	50.00	X
	\$ 2,918.08	
	=====	

Dollars : Two Thousand Nine Hundred Eighteen And Cents Eight Only.

HUP MOTOR TRADING & SERVICE

*[Signature]*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 1519.4  
202  
12/15/22  
820  
2035.52  
202  
1628

哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3158/10/24 Your Ref: \_\_\_\_\_ Date: 10th Oct 2024

MR KOH YOK HUAT  
BLK 381A, #10-1529  
YISHUN RING RD, S(761381)

Supplementary Bill for HONDA VEZEL 1.5 (A) SUV- SLA 7424 S

1 pc front bumper lower spoiler skirt garnish	gum	\$ 382.50
	Less 20%	\$ 76.50
		<u>\$ 306.00</u>
		=====

Dollars : Three Hundred And Six Dollars Only.

HUP MOTOR TRADING & SERVICE

\_\_\_\_\_