



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

* zoomautowerks@gmail.com

not Authorised

21 October 2024

REG NO.: SNQ 9019 H
MAKE/MODEL: HYUNDAI AVANTE

moras
9/10/24
1/5 # 5600
take photo after repair
4 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front bonnet	\$ 1,911.00 X
1	Front headlamp -LH	\$ 3,034.90 ✓
1	Front headlamp lower bracket	\$ 127.60 ✓
1	Front grille	\$ 1,215.00 X
1	Front grille top garnish	\$ 156.00 X
1	Front grille logo	\$ 91.00 X
1	Front bumper	\$ 525.00 ✓
1	Front bumper fog lamp	\$ 200.30 X
1	Front bumper fog lamp grille	117.00 \$ 150.20 ✓
1	Front bumper reinforcement	\$ 696.00 X
2	Front bumper side retainers	\$ 120.40 X
1	Front bumper top rubber seal	\$ 65.00 X
1	Front bumper undercover	\$ 168.00 X
1	Front bumper PDC sensor	\$ 225.00 X
1	Front bumper lower beam	\$ 265.00 X
1	Front bumper logo	\$ 91.00 X
1	Front fender -LH	\$ 677.30 ✓
1	Front fender inner shield	\$ 120.80 X
1	Front wheel rim -LH	680 \$ 1,017.30 ✓
1	Front wheel hub	\$ 189.50 ✓
1	Front wheel bearing	\$ 155.80 ✓
1	Front shock absorber	\$ 424.50 ✓
1	Front knuckle arm	423.50 \$ 455.80 ✓
1	Front lower arm	\$ 435.00 ✓
		\$ 12,517.40
	Less 10%	\$ 1,251.74
		\$ 11,265.66

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	\$ 80.00 30
1	Front fender inner shield clip (1 set)	\$ 65.00 X
1	Front tyre	\$ 450.00 X
		\$ 595.00

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$	80.00	20
2	To remove and refit front sensor.	\$	150.00	30
3	To remove and refit front undercarriage.	\$	400.00	120
4	To conduct wheel alignment.	\$	180.00	80
5	To apply undercoating.	\$	180.00	30
6	Panel beating.	\$	1,600.00	480
7	To re-spray painting on the affected areas.	\$	1,500.00	800
		\$	4,090.00	

GRAND TOTAL :

\$ 15,950.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6790.1
 202
 5432.08
 30
 1560
 7022.08
 201
 5617