

TSL AUTO PRO SELECTION PTE LTD

BLK 1 KAKI BUKIT AVE 6 #01-06 AUTOBAY @KAKI BUKIT
SINGAPORE 417883

TO	: NTUC	DATE	17/10/2024
VEHICLE NO	: SJL6704G (2008)		Veron
VEHICLE MODEL	: HONDA JAZZ		
CHASSIS NO	: JHMGE68509S209858		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>torn</i>	1	\$ 585.70	\$ 585.70
2	REAR BUMPER SIDE HOLDER <i>new</i>	1	\$ 24.50	\$ 24.50
3	TAILLAMP <i>new</i>	1	\$ 296.20	\$ 296.20
4	REAR FENDER <i>Replaced</i>	1	\$ 773.90	\$ 773.90
5	REAR FENDER INNER SHIELD <i>torn</i>	1	\$ 91.70	\$ 91.70
6	REAR SHOCK ABSORBER <i>3 x HP new</i>	1	\$ 296.70	\$ 296.70
7	REAR WHEEL HUB C/W BEARING	1	\$ 356.30	\$ 356.30
8	REAR AXLE	1	\$ 985.80	\$ 985.80

TOTAL PRICE: \$ 3,410.80

LESS 20% \$ 682.16

SUB TOTAL PRICE: \$ 2,728.64

677.40

541.92

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
2	REAR BUMPER LOWER SPOILER <i>used</i>	1	\$ 1,200.00	\$ 1,200.00
3	REAR FENDER INNER SHIELD CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
4	REAR FENDER SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
5	REAR FENDER GLASS SEALANT <i>new</i>	1	\$ 40.00	\$ 40.00
6	REAR WHEEL RIM <i>cut</i>	1	\$ 880.00	\$ 880.00
7	REAR TYRE <i>HP new</i>	1	\$ 280.00	\$ 280.00
8	ROCKER PANEL SIDE SKIRTING <i>used</i>	1	\$ 1,000.00	\$ 1,000.00
9	ROCKER PANEL SIDE SKIRTING CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00

TOTAL : \$ 3,540.00

22/0

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	600	
3	WIRING CHECK	\$ 50.00	30	
4	TO APPLY TUFF COAT	\$ 150.00	40	
5	TO REMOVE UPHOLSTERY	\$ 150.00	40	
6	TO REMOVE REAR FENDER GLASS	\$ 80.00	x	
7	TO REMOVE REAR UNDERCARRIAGE	\$ 380.00	x	
8	TO PERFORM WHEEL ALIGNMENT	\$ 150.00	80	

TOTAL: \$ 3,160.00

1290

ESTIMATE REPORT

TOTAL PARTS COST:	\$	6,268.64
TOTAL LABOUR COST:	\$	3,160.00
TOTAL REPAIR COST:	\$	9,428.64

total : 404192

L/S : 3.2K

0.5 Days

\$ 3.2K

3.2K

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: