

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref :- Date: 11<sup>th</sup> Oct 2024

Our Ref : CS/TP24100193/Eqh3e2

## M/s Jenny A/P John Pillay

06-30 Bendahara A Jalan Yahya Awal Bukit Saujana 81100 Johor Bahru Johor Malaysia (The Motor Claims Department)

Dear Sirs/Madam,

## AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE JUY 5236 ACCIDENT ON 24/09/2024

Instruction was received to inspect the vehicle Reg. No. JUY 5236. The inspection was conducted on 10/10/2024 at the premises of M/s LKK Auto Consultants Pte Ltd, 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933.

The following vehicle information was recorded:

Registration Number : JUY 5236

Make/Model : Yamaha Lagenda 115Z

Year of Registration : 2022 Body Colour : Blue

Chassis Number : PMYUE1510N0160368

Engine Capacity : 114 cc Speedometer Reading : 40717 km

The vehicle sustained damages at the front, rear portion and n/s body. The chassis frame affected due to collision. (Details see photographs enclosed)

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

(a) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES** (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989, that:

no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle. and we therefore recommend it to be written off as "Total Loss"

Market Value

RM 4,900.00 (est)

Vehicle Inspected By:

CHEN TSUE YEE
Automotive Assessor

7

K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIArd, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.