



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 188903663G

Page 1 / 3

ESTIMATE

Date	: 04/11/2024	Reg No	: XD4671G
To	: ECICS LIMITED	Model	: MAN / TGM 18.280 4X2 BB
Attn.	:	Chassis No	: WMAN08ZZ7AY244448
Office / Mobile	:	Engine No	:
Email Address	:	Quotation No.	: 221152
		Ref. No.	: GBE/SVC/SALES-HQ/ 194-04/10
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/10/2024
Attn.	: AMENCIA	Policy No.	: BVFCSB0006702419
Office / Mobile	:	Claim Type	: TP CLAIM - ECICS INSURANCE
Email / Fax No.	: Amencia@goldbell.com.sg	Workshop	: 8 TUAS AVE 18


S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		SYNTHETIC BUMPER <i>cm</i> ✓	1	3,600.00	-10	3,240.00	3,240.00
2		BUMPER END PANEL RH <i>cm</i> ✓	1	130.00	-10	117.00	117.00
3		BUMPER END PANEL LH <i>mis</i>	1	130.00	-10	117.00	117.00
4		TRIM ?	2	130.00	-10	117.00	234.00
5		BUMPER GARNISH LOWER RH ?	1	338.00	-10	304.20	304.20
6		BUMPER GARNISH LOWER LH ?	1	338.00	-10	304.20	304.20
7		HEADLAMP RH ?	1	1,690.00	-10	1,521.00	1,521.00
8		HEADLAMP LH ?	1	1,690.00	-10	1,521.00	1,521.00
9		AUXILIARY HEADLAMP FLASHER <i>cm</i> ✓	1	455.00	-10	409.50	409.50
10		ENTRY MUDGUARD RH ?	1	2,860.00	-10	2,574.00	2,574.00
11		ENTRY MUDGUARD LH <i>X</i>	1	2,860.00	-10	2,574.00	2,574.00
12		STEP, LH <i>cm</i> ✓	1	455.00	-10	409.50	409.50
13		FLASHER ?	1	156.00	-10	140.40	140.40
14		WHEEL NUT COVER RING AXLE <i>bt</i> ✓	1	234.00	-10	210.60	210.60
15		WIND DEFLECTOR ?	1	494.00	-10	444.60	444.60
16		PILLAR LINING ?	1	585.00	-10	526.50	526.50
17		REAR LAMP RH <i>bn</i> ✓	1	491.40	-10	442.26	442.26
18		REAR LAMP LH <i>bn</i> ✓	1	491.40	-10	442.26	442.26

PARTS TOTAL : 15,532.02

SPECIAL NETT ITEMS

1	STICKER <i>m</i> ✓	1	0.00
2	NUMBER PLATE <i>mis</i> ✓	2	35 50.00
3	60KM/H <i>m</i> ✓	1	30.00

PARTS TOTAL: 80.00





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638882 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638882 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co Reg No: 1989036835

Page 2 / 3

ESTIMATE

Date	: 04/11/2024	Reg No	: XD4671G
To	: ECICS LIMITED	Model	: MAN / TGM 18.280 4X2 BB
Attn.	:	Chassis No	: WMAN08ZZ7AY244448
Office / Mobile	:	Engine No	:
Email Address	:	Quotation No.	: 221152
		Ref. No.	: GBE/SVC/SALES-HQ/ 194-04/10
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/10/2024
Attn.	: AMENCIA	Policy No.	: BVFCSB0006702419
Office / Mobile	:	Claim Type	: TP CLAIM - ECICS INSURANCE
Email / Fax No.	: Amencia@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	2100 2500.00
2	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1400 1800.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS	180 280.00
4	TO DISMANTLE AND CHANGE NEW 1 PC REAR UNDERRUN BUMPER	0.00
5	TO DISMANTLE AND CHANGE NEW 2 PCS REAR ALUMINIUM SHEET	0.00
6	REAR LEFT HAND SIDE POLE DENTED, TO PROVIDE LABOUR TO PULL IT BACK WITH REPAIR WORK.	0.00
7	TOTAL LABOUR FOR REAR DECK	3600 5040.00

LABOUR TOTAL :	9,620.00
SUB-TOTAL :	25,232.02
GST @ 9% for \$ 25,232.02	2,270.88
GRAND TOTAL (S\$) :	27,502.90



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 6 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No: 198903963G

Page 3 / 3

ESTIMATE

Date	: 04/11/2024	Reg No	: XD4671G
To	: ECICS LIMITED	Model	: MAN / TGM 18.280 4X2 BB
Attn.	:	Chassis No	: WMAN08ZZ7AY244448
Office / Mobile	:	Engine No	:
Email Address	:	Quotation No.	: 221152
		Ref. No.	: GBE/SVC/SALES-HQ/ 194-04/10
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 04/10/2024
Attn.	: AMENCIA	Policy No.	: BVFCB0006702419
Office / Mobile	:	Claim Type	: TP CLAIM - ECICS INSURANCE
Email / Fax No.	: Amencia@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

PREPARED BY : AMENCIA

DATE / TIME : 05/11/24

SURVEYOR : RASUL

MOBILE NO : 96010068

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMPSUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Reg after repair

10 days



AIRMAN

